



Volvo V 60:			
Vinnumber:	YV1ZWH1V2R1617822	Versionname:	
First Registrationdate:	5/10/2023	Fiscalpower:	
Expertise Mileage:	167079	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3403
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS base		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		
Limited Technical Inspection			
Tyres			
Summer tyres:	245/45/18/98 W		
	Fr.L.	Michelin: 5 mm	Fr.R. Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R. Michelin: 5 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			245/45 R 18 98 W
Tyre size FR			245/45 R 18 98 W
Tyre size RL			245/45 R 18 98 W
Tyre size RR			245/45 R 18 98 W
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		
Total cost ex VAT			1744,59
Backrest cover FL, Damaged, Acceptable			0,00



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)	356,09
--	--------




Bumper moulding F, Dent(s) and scratch(es), Repair and paint (complete)	161,81
---	--------



Bumper grille, Dent(s) and scratch(es), Replace	112,64
---	--------



Windscreen, Stone chip(s), Windscreen repair	75,44
--	-------



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Alloy rim RL polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Roof pillar L, Scratch(es), Acceptable	0,00
--	------



Charging cable (normal), Missing, Check	0,00
---	------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Side window trim FR, Missing, Replace and paint	221,77
---	--------



Door FR, Not original part, Check	0,00
-----------------------------------	------



Wing RR, Repaired, Acceptable	0,00
-------------------------------	------

