Citroën Berlingo 102pk Closed van L2H1 Airco Navi Cruise Carplay Euro6 Maxi

VR7EFYHYCMJ801683 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	vr7efyhycmj801683
First Registration	12/2/2021
Country of Origin	Netherlands
Mileage	143,205 km
Citroën Berlingo 102pk Close...	Lot: 47Veghel, NetherlandsFirst registration: December 2, 2021Mileage: 143,205 km102 hp
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	Vehicle location:Veghel, NetherlandsCalculate delivery time and price
Vehicle location	
Engine Output HP/PK	102 hp
Power type	Diesel
Emission norm	Euro 6
Cilinder Amount	4
Distribution type	Belt
Engine displacement (cc)	1499
Engine Type	DV5RD
Amount of Axles	2
Undercarriage	Wheeled
Tyre condition Axle 1 Left (MM)	6 mm
Tyre condition Axle 1 Right (M...	6 mm
Tyre condition Axle 2 Left (MM)	4 mm

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Tyre condition Axle 2 Right (M...	4 mm
Tyre size Axle 1	205/60 R16
Tyre Size Axle 2	205/60 R16
Wheelbase	298 cm
Type Lights	Halogen
Door opening height	110 cm
Door opening width	123 cm
Inner height	118 cm
Inner length	213 cm
Inner width	124 cm
Space between wheelarches	123 cm
Material floor	Wood
Van size	L2H1
Mileage	143210 km
Airco option	airco
Number of seats	2
Type of cabin	Single
Type of Radio	DAB
Empty weight	1477 kg
Registration Date	2021-12-02
Towing weight	1000 kg
M.O.T. approved till	2026-12-02
NAP	Logisch
Gross Vehicle Weight (GVW)	2355 kg
VIN / Serial Number/ Chassisn...	VR7EFYHYCMJ801683
Brand	Citroën
Model	Berlingo
Product Group (Tax)	Closed Van
Country of origin	NL
Axle capacity 1	1200 kg
Axle configuration	2002-10-04
Colour	white
Type of drive	FWD
Type extended	Berlingo 102pk
Max load capacity	878 kg
Vehicle Height (cm)	184 cm
Vehicle Length (cm)	648 cm
Vehicle Width (cm)	178 cm
Request Transaction Id	879071a3-e25a-4fca-8cdd-a5991354651f
Amount of forward gears	5
Transmission	Manual

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Truck ID	70339629
Lot	47
First registration	December 2, 2021
November 3, 2026 at 02	23 PM

Damage & Condition

All known damages are listed and shown in photos for full transparency.

1 damage reported | Worst: Minor




Multiple
Cosmetic Damage
.

Minor



Front / Right



Back / Left




19°c
Zender valt weg
15:11
Profiel deactiveren
Thema's
Audio-instelling...
Scherm uit
Profiel geactiveerd
Profiel 1
OPTIES
Profiel 1
Profiel 2
Profiel 3



19°C
Zender valt weg
15:11
Abenhoefweg
Zone niet in kaart gebracht
MENU
3D
Zoeken...


19°C
100% NL
15:10
Stop and Start
OFF ON
Antispinregeling
OFF ON
Bandenspan.contr.
Diagnose
Besturingsfuncties
Instellingen van de auto.


19°C | |
Zender valt weg
| | 15:11
Voor het verbeteren van deze functies kan informatie met betrekking tot autogegevens en autolocatie worden verzonden naar uw verbonden apparaat.
Apple CarPlay
Connected-apps
Android Auto
OPTIES |
Connectiviteit


19°C | |
Zender valt weg
| | 15:11
Telefoon koppelen
Geen enkele telefoon verbonde
OPTIES |
Contacten


19°c
15:10
Band
FM
FM 100% NL
94.90 MHz Popmuziek
1
2
3
4
5
OPTIES
Frequentie
Geheugen
Lijst
BRONNEN


AUTO
SET +
SET –
LIMIT
CRUISE


OK
SRC/TEL


0
km/h
56.2 Km
143217 Km
SET 000






BERLINGO VAN
VOORDAT U GAAT RIJDEN
CITROËN
NE. 19K9C.E670
GARANTIE- EN ONDERHOUDSBOEKJE








































A/C


19°C
Zender valt weg
15:11
Profiel deactiveren
Thema's
Audio-instelling...
Scherm uit
Profiel geactiveerd
Profiel 1
OPTIES
Profiel 1
Profiel 2
Profiel 3


19c
Zender valt weg
15:11
Telefoon koppelen
Geen enkele telefoon verbonden
OPTIES
Contacten



















