



Tesla Model Y:

Vinnumber:	LRWYGCEK8NC349730	Versionname:	
First Registrationdate:	20/06/2022	Fiscalpower:	
Expertise Mileage:	106703	Power Kw:	378
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2211
Fueltype:	Electric		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	Tow bar removable
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

255/40/20/101 W				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				3.0
Tyre size FL				255/40 R 20 101 W
Tyre size FR				255/40 R 20 101 W
Tyre size RL				255/40 R 20 101 W
Tyre size RR				255/40 R 20 101 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Total cost ex VAT	1004,70
Interior, Damaged, Acceptable	0,00



Bumper F, Scratch(es), Repair and paint (complete) 355,89



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Wing RL, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Boot lid covering R, Scratch(es), Smart repair 116,69



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Door FR, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Repair and paint (complete)

133,03



A-pillar right, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Acceptable

0,00



Wing RR, Dent(s) and scratch(es), Acceptable

0,00

