

» Overview

Order number: 1002399104
Order completed: 22.04.2026 08:25
Report number: 10468332
VIN: VSSZZKJXRR134125



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	Limousine
Make:	Seat
Model:	Ibiza
Manufacturers and type code:	7593 / ANH
Date of first registration:	23.04.2024
Mileage:	7,618 km
Proof of mileage:	ReadOff
Exterior colour:	Saphirblau
Roof colour:	Saphirblau
Propulsion:	Front
Fuel:	Petrol
Engine size (cc):	1,000 ccm
Performance:	85 kW (116 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	3
Euronorm:	Euro 6
Number of doors:	5
Number of seats:	5
Gearbox:	Manual 6-speed
Upholstery type:	Lining fabrics
Interior colour:	Grau-Schwarz-Swing
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	04.2027
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	

"Standard Plus" version	Drawers under front seats
2 reading lights in front	Driving on the right
3-cylinder gasoline engine 1.0 l/85 kW, TSI base engine: TJ4, "TSI"	Electronic immobilizer
3-cylinder SI engine 1.0 l unit 05C.B	Electronic stability control (ESC)
3-point seat belt for center rear seat	Emission standard, WLTP3 M1, N1-l//EU6EA
3-point seat belts in front, with belt clamping device, without height adjustment	Equipment options subset for Germany
3-point seat belts, outer rear with ECE label	Extended and proactive pedestrian and cyclist protection
4 doors	Exterior mirror housings and various add-on parts in body color
6 speakers (passive)	Exterior mirrors, power-folding/adjustment, heated
6-speed manual transmission "M6"	External, USB type C, only data socket(s)
Activated carbon canister (Evaporative Emission Control System (EVAP))	Forward collision warning incl. autonomous emergency braking, without adaptive cruise control
Advanced driver attention & drowsiness monitor	Fresh air intake system with combination filter
Airbag on driver and front passenger side, without knee airbag, with front passenger airbag deactivation	Front head restraints
Alloy wheels 5.5J x 15	Front stabilizer bar
All-season tires 185/65 R15 88V	Front-wheel drive
All-season tires with 15-inch alloy rims	Fuel system for fuel-injected SI engine (tropicalized)
Alternator 140 A	Gearshift knob/handle in leather
Antenna for AM/FM reception, "diversity"	Hand brake lever handle in leather
Antifreeze up to -25 degree Celsius tolerance up to -30 degree C	Hatchback
Axial and vertical adjustable steering column	Headlight range control
Battery 320 A (49 Ah)	Heat-reflecting windshield
Body-colored bumpers	Hill start assist
Breakaway interior rearview mirror, auto-dimming	Initial standard fuel filling
Breakdown kit	In-plant control of self-collection
Carrier frequency 433.92 MHz-434.42 Mhz	Installation differentiation for transmission MQ 200_GA -- vehicle components --
Center armrest in front	Instrument cluster, km/h speedometer
Central locking w/ radio remote control, interior controls, without SAFELOCK	Interior package: double floor, drawer under right seat, storage compartment under left seat, front center armrest
Child seat anchors for child seat system ISOFIX	Lane keeping system
Chrome package	Leather-wrapped multi-function sports steering wheel
Climatronic with impact pressure control, CFC-free	LED headlamps
Comfort package	Left exterior mirror, convex
Control of series production	Left-hand drive
Cruise control system and speed limiter	LongLife Service Regime
Decorative inserts	Luggage compartment cover, folding
Digital Cockpit	Luggage compartment trim (design 1)
Digital radio reception	Luxury equipment
Disc brakes in front (Geomet D)	Manual height adjustment for left front seat
Disc brakes in rear (Geomet D)	Manual in German
Door and side trim panel	Mobile phone interface
	Mounting fixture in luggage compartment

Multi-function display/trip computer active info display "Entry"	Standard dashboard
Nameplate set in basic style	Standard decorative trims
Navigation system	Standard design
Navigation system - High	Standard license plate lighting
No special edition	Standard manufacturing sequence
No special purpose vehicle, standard equipment	Standard paint coating
Non-smoker's package	Standard pedal cluster
Not hot country	Standard rear axle
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Standard seats in front
Operating permit, alteration	Start-stop system with regenerative braking
Optional infotainment system (MIB3)	Sun visors with mirror, airbag label on front passenger sun visor
Pan-European emergency call service	Suspension range 04 installation control only, no requirement forecast
Park distance control	Three rear head restraints
Part set without country-specific prescriptive standard	Tire pressure monitoring system
Plane luggage/load compartment floor in rear	Tires without specification of tire brand
Power steering	Tool kit
Power windows with comfort operation and circuit breaker	Trims for alloy wheels
Protective side molding	Type approval country Germany
Rear combination lamp, standard design	Type sign and company logo
Rear exhaust tailpipe (standard)	Unsplit molded headliner
Rear floor panel module, type 1	Unsplit rear seat bench, split folding backrest
Rear fog lamp	Variant
Rear overhang, short	Vehicle class differentiation -6F0-
Rear shock absorption	Vehicles with special upgrade measures
Rear window wiper and washer system with intermittent control	Vent
Reduced price package	Visual and acoustic seat belt reminder, electric contact in front and rear
Refrigerant R1234yf	Voice control
Regional code " ECE " for radio	Weight range 4 installation control only, no requirement forecast
Right exterior mirror, convex	Wheel bolts with anti-theft protection (unlockable)
SEAT CONNECT gen3 - Safety, service, remote access and online infotainment	Wheelbase
SEAT Connect Plus - 3 years	Windshield wiper intermittent control with light/rain sensor
Seat trim covers in fabric	Wired & Wireless App-Connect
Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature	With dynamic road sign display
Service indicator 30 000 km or 2 years (variable)	With multifunction camera
Shock absorption in front	With UNECE CS (R155) without SU (R156)
Side airbag in front with curtain airbag	Without "drive select"
Side and rear windows in heat-insulating glass	Without add. lights (interior lighting)
Single-tone horn	Without additional front underbody guard
Special identification label for EC for M1 passenger vehicles	Without additional noise suppression measures for passenger compartment
Special price	Without additional side body covers (stone guard)
Standard air cleaner	Without additional tires
Standard climatic zones	

Without alternative drive system
Without applications
Without auxiliary heater/parking heater
Without backrest release for front seats
Without camera systems/accident sensors
Without CD changer/CD player
Without CD/DVD for navigation
Without customized installation
Without decorative films/emoblems
Without delivery equipment
Without differential lock
Without ECO function
Without extended safety system
Without fire extinguisher
Without first aid kit and warning triangle
Without floor mats
Without front fog lamps
Without headlamp washer system
Without heat accumulator/auxiliary heater
Without heated washer nozzles
Without interior light in footwell
Without lane change assist
Without light control
Without luggage nets/pockets on backrests
Without lumbar support in seat backrests
Without rear spoiler
Without roof insert (standard roof)
Without roof rails/roof load rack
Without seat heater
Without second battery
Without special body measures
Without special color trim
Without special specifications
Without surface protection, with additional transport protection measures
Without trailer hitch
Without washer fluid level indicator

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Goodyear	Front	Left	All season	Aluminium	185/65 R 15 88 V	7.0 mm
Goodyear	Front	Right	All season	Aluminium	185/65 R 15 88 V	7.0 mm
Goodyear	Rear	Left	All season	Aluminium	185/65 R 15 88 V	8.0 mm
Goodyear	Rear	Right	All season	Aluminium	185/65 R 15 88 V	8.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Repair kit present: Yes

Repair kit expiration date: 02.2028

Compressor present: Yes

No devaluation factors available

» Usage Damages

Nr	Location	Damage type	Repair type
1	Windscreen	Stone chip(s)	Acceptable

» Commercial devaluation

Known previous damages:	Yes
Previous damages detectable:	No
Repainting present:	Yes
Repainting professionally executed:	Yes
Paint thickness measurement performed:	Yes - with abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Fully comprehensive harm		€ 1,582.07
Total without VAT:				€ 1,582.07

PAINTTHICKNESS MEASUREMENT RESULTS

Part	Paint (µm)
Paint thickness Roof (µm)	185.0

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

VSSZZZKJXRR134125

VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Sufficient, Wet

Lifting platform/lifting equipment used:

No

Testdrive carried out:

No

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Sill outer L



Sill outer R




Chassis nr



Wheel FL



Wheel FR



Wheel RL




Wheel RR



Central console



Engine compartment



Documents




Interior arrangement



Registration Certificate




Paint thickness Roof



History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



GPS/Radio

» Devaluation Damages

USAGE DAMAGES

1 - Windscreen - Stone chip(s) - Acceptable

