AUDI Q3


Vehicle information

Make:	**AUDI**	License:	**2CCG279**
Gearbox:		Body color:	
Model:	**Q3**	VIN:	**WAUZZZF33N1099639**
Fuel type:		Power:	**110 kW**
Version:	**1.4 45 TFSI E S TRONIC**	First registration	**01/06/2022**
Mileage:	**38324 km**	N° of doors:	


Damage summary

Interior	1
Rear	1
Right	3
Roof & others	1

Commercial pictures






























Options according to the inspector

GPS	**Yes**

Damages

Bodywork
Damaged
Acceptable
Roof & others












Charging cable (normal)
Missing
Check
Rear



Door RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right






Interior
Damaged
Acceptable
Interior




Wing RR
Scratch(es)
Paint
Right




Wing trim RR
Scratch(es)
Replace
Right




Tyres

Front Left

Summer

215/65/17/99/V

Goodyear

6.0 mm

Front Right

Summer

215/65/17/99/V

Goodyear

6.0 mm

Rear Left

Summer

215/65/17/99/V

Uniroyal

6.0 mm

Rear Right

Summer

215/65/17/99/V

Uniroyal

6.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Maintenance	**21700.0**
Maintenance	**OK**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**1**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**No**
Repair kit	**Yes**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Statutory inspection	**01/06/2028**	Statutory inspection	**OK**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.