



Citroën C5 Aircross: [REDACTED]

Vinnumber:	VR7ACYHZKML026216	Versionname:	
First Registrationdate:	2/06/2021	Fiscalpower:	
Expertise Mileage:	118398	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2707
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	205/55/19/97 H			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 19 97 H
Tyre size FR				205/55 R 19 97 H
Tyre size RL				205/55 R 19 97 H
Tyre size RR				205/55 R 19 97 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	266,06
Seat cover FL, Worn, Acceptable	0,00



Bonnet, Stone chip(s), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Wing trim FL, Scratch(es), Acceptable 0,00



Bumper trim R, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Door RR, Dent(s) and scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



