



BMW SERIES			
Vinnumber:	WBA7M710607L16002	Versionname:	
First Registrationdate:	30/05/2022	Fiscalpower:	
Expertise Mileage:	126729	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3727
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	20000.0		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	195/55/16/91 V		
	Fr.L.	Continental: 5 mm	Fr.R. Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 6 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			6.0
Tyre size FL			195/55 R 16 91 V
Tyre size FR			195/55 R 16 91 V
Tyre size RL			195/55 R 16 91 V
Tyre size RR			195/55 R 16 91 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			537,98
Seat cover FL, Worn, Acceptable			0,00




Backrest cover FL, Scratch(es), Acceptable	0,00
--	------



Seat cover FR, Stain, Cleaning	29,16
--------------------------------	-------




Bumper F, Dent(s) and scratch(es), Spot repair	148,33
--	--------



Door FL, Dent(s), Paintless dent repair	95,47
---	-------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Spot repair	148,33
------------------------------------	--------



Boot cover, Scratch(es), Acceptable	0,00
-------------------------------------	------



Boot lid covering R, Scratch(es), Smart repair	116,69
--	--------



Mirror side repeater R, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00



Bodywork, Not original part, Check

0,00

