



RENAULT Clio: 5340-MRB

Vinnumber:	VF1RJA00372027877	Versionname:	Evolution dCi 100 (74kw) berlina con portón 74kW
First Registrationdate:	29/04/2024	Fiscalpower:	5P manual
Expertise Mileage:	300233	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Radio
Number keys remote	2	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Manual climate control	

Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Boot lid covering R, Scratch(es), Replace			



Interior, Dirty, Cleaning



Registration document, Missing, Repair/replace (lump sum)



Wing FL, Dent(s), Repair and paint (complete)



Wheel bolt cover FL, Scratch(es), Replace



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Windscreen, Stone chip(s), Replace



Wheel bolt cover RR, Missing, Replace



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable




Wheel bolt cover FR, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering



Aerial, Missing, Replace

