

## 2-FGV-189

2-FGV-189 · Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06 · 22 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-FGV-189	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ8RR122667
Model	Arona	Cylinder Capacity	999 <sup>cm<sup>3</sup></sup>
Model Versions	Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	06-05-2024
Color	Black	Odometer	64.696 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	85	Number Headrests	5

Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 <sup>mm</sup>	Michelin	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Rear Left	4 <sup>mm</sup>	Michelin	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Front Right	2 <sup>mm</sup>	Michelin	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Rear Right	4 <sup>mm</sup>	Michelin	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Spare Tire Type	Compressor					

## Damages



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small scratch(es)

Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Left Rear

Damaged

Rim repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Scratch(es)

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Scratch(es)

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Left

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Left

Scratch(es)

Spray

No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Door-edge chipped	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Front Right	small dents / small scratches	Restyle / Touch-up	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Small dent(s)	Restyle	No





Damage Part  
Overfender

Damage Type  
Scratch(es)

Repair Type  
Replace

Acceptable  
No



Damage Part  
Bumper - Rear

Damage Type  
Scratch(es)

Repair Type  
Spray

Acceptable  
No