SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

2-ESY-927

2-ESY-927 · Titanium comfort/winterpack 1.0i ecoboost 100pk 74kw · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-ESY-927
Manufacturer	FORD
Model	Fiesta
Model Versions	Titanium comfort/winterpack 1.0i ecoboost 100pk 74kw
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2023
KW	74
Fuel Type	Gasoline

VIN	WF0JXXGAHJPD20907
Cylinder Capacity	998 cm3
Transmission Type	Handmatig geschakelde transmissie
First Admission	18-01-2024
First Registration	18-01-2024
Odometer	65.851 Km
Numer Of Keys	2
Interior	Darkgrey - Cloth
Number Headrests	5

Images
























1 3 5
2 4 6 R








Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Audio System	Leather steering wheel
Automatic air conditioning	Rear parking sensors
Bluetooth car kit	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel – Heated
Electric rear windows	Windscreen – Heated

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 mm	Delinte	195 mm	60 mm	15 inch	Summer
Rear Left	3 mm	Continental	195 mm	60 mm	15 inch	Summer
Front Right	6 mm	Delinte	195 mm	60 mm	15 inch	Summer
Rear Right	3 mm	Continental	195 mm	60 mm	15 inch	Summer
Spare Tire Type	Compressor					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No