MACADAM










RENAULT CLIO SOCIÃ‰TÃ‰: GA-351-DR

Vinnumber:	**VF1RJA00667689468**	Versionname:	**RENAULT CLIO SOCIÃ‰TÃ‰ Air Nav SCe 65 VF [5P] 5-65CH-4cv (bi-corps VU-)**
First Registrationdate:	**22/06/2021**	Fiscalpower:	
Expertise Mileage:	**71468**	Power Kw:	**48**
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Category	**VS**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Windows electric R		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**185/65/15/88 H**			
	Fr.L.	**Bridgestone: 70%**	Fr.R.	**Bridgestone: 75%**
	Re.L.	**Hankook: 40%**	Re.R.	**Hankook: 40%**

Tyre profile depth FL	**3.7**
Tyre profile depth FR	**3.4**
Tyre profile depth RL	**5.7**
Tyre profile depth RR	**5.7**
Tyre size FL	**185/65 R 15 88 H**
Tyre size FR	**185/65 R 15 88 H**
Tyre size RL	**185/65 R 15 88 H**
Tyre size RR	**185/65 R 15 88 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Interior, Dirty, Chemical cleaning




Tyre FL, Out of tolerance, Replace




Tyre FR, Out of tolerance, Replace




Wheel cover FR, Deformed / Strained, Replace




Door FL, Dent(s), Repair and paint (complete)




Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Paint




Bumper moulding F, Unclasped, Dismount/Mount




Number plate F, Deformed / Strained, Repair/replace (lump sum)




Wing RR, Scratch(es), Paint




Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Acceptable




Wing FR, Dent(s), Repair and paint (complete)




Bumper R, Scratch(es), Paint





Roof, Dent(s), Repair and paint (complete)




ALPHABET

Historique Maintenance

Immatriculation: **GA-351-DR** Date de 1ère immatriculation: **22/06/2021**

Modèle: **Renault CLIO SOCIÉTÉ Air Nav SCe 65 VF [5P] 5-65CH-4cv (bi-corps VU-)**

Date	Kilométrage	Fournisseur	Descriptif
15/07/2026	70.998	TOURS CENTRE AUTOMOBILE	Frais de participation à l'environnement
			Rinçage du circuit de refroidissement
			Disque de frein - Avant (Remplacement)
			Disques/Tambours de freins
			Essai routier
			Plaquettes/Machoires de freins
			Essuie - Glace Arrière (Remplacement)
			Essuie-Glace
			Batterie (Remplacement)
			Batterie
			SERENITE
			LIQUIDE DE REFROIDISSEMENT RPLT
			DISQUES PLAQUETTES AV RPLT
			BALAI ESSUIE GLACE AR
			BATTERIE RPLT
			RECYCLAGE
			Pieces
			Entretien - Autre
			Pieces
18/07/2025	60.875	SAS SCAUTO	FILTRE CLIM RPLT
			REVISION ET CLIM ET AIR ET CARBURANT
23/05/2025	58.224	SAS SCAUTO	BALAIS ESSUIE GLACE AV
26/09/2024	52.589	GARAGE MICHEL TRAISNEL	LIQUIDE DE FREIN
			SERENITE
			RECYCLAGE
26/09/2023	33.716	SAINT LAURENT AUTOS	SERENITE
01/08/2023	30.417	SAINT LAURENT AUTOS	REVISION
23/09/2022	20.052	BLAYE AUTOMOBILE	SERENITE