MACADAM









PEUGEOT PARTNER: FT-245-DG

Vinnumber:	**VR3EFYHYCLN514688**	Versionname:	**PEUGEOT PARTNER BLUEHDI 100 S&S 650KG STAND ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**1/10/2020**	Fiscalpower:	
Expertise Mileage:	**88315**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Dark Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
GPS big screen color		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Steering wheel multifunctional		Rear view camera	
Type of climate control	**Manual climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**195/65/15/91 H**			
	Fr.L.	**Continental: 90%**	Fr.R.	**Continental: 90%**
	Re.L.	**Goodyear: 20%**	Re.R.	**Goodyear: 25%**

Tyre profile depth FL	**2.2**
Tyre profile depth FR	**2.1**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**6.4**
Tyre size FL	**195/65 R 15 91 H**
Tyre size FR	**195/65 R 15 91 H**
Tyre size RL	**195/65 R 15 91 H**
Tyre size RR	**195/65 R 15 91 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key, Missing, Repair/replace (lump sum)



Seat cover FR, Stain, Cleaning









Steering wheel, Scratch(es), Repair/replace (lump sum)




Floor mat F, Burned, Smart repair




Tyre FL, Out of tolerance, Replace




Wheel cover FL, Missing, Replace




Tyre FR, Out of tolerance, Replace




Wheel cover FR, Missing, Replace




Wing FL, Dent(s) and scratch(es), Repair and paint (complete)






Door FL, Dent(s) and scratch(es), Repair and paint (complete)







Side wall RL, Scratch(es), Polish





Bumper F, Scratch(es), Acceptable




Bumper F, Scratch(es), Paint





Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)





Outer sill R, Dent(s), Repair and paint (complete)




Rubber seal for boot lid, Unclasped, Dismount/Mount




Bumper R, Scratch(es), Repair and paint (complete)







Boot door panel RR, Rust, Paint






Boot door panel RL, Dent(s) and scratch(es), Acceptable






Brand badge R, Missing, Replace



Bumper corner RR, Scratch(es), Acceptable




Bumper corner RL, Scratch(es), Acceptable




Bodywork, Not original part, Sticker removal small



ALPHABET

Historique Maintenance

Immatriculation: **FT-245-DG** Date de 1ère immatriculation: **01/10/2020**

Modèle: **Peugeot PARTNER BLUEHDI 100 S&S 650KG STAND ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
10/07/2026	82.009	GARAGE JCM	DIVERS CARROSSERIE
09/07/2026	82.009	GARAGE JCM	DIVERS ECLAIRAGE
08/07/2026	82.009	GARAGE JCM	RETROVISEUR D RPLT
10/03/2026	77.606	GARAGE JCM	POT CATALYTIQUE FAP RPLT
18/02/2026	77.257	GARAGE JCM	INJECTEUR ADBLUE RPLT
09/01/2026	75.094	GARAGE JCM	FILTRE CLIM RPLT
			BALAIS ESSUIE GLACE AV
			REVISION
07/11/2025	69.715	GARAGE JCM	DIVERS ELEC
			BATTERIE RPLT
24/07/2025	63.250	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
16/07/2025	63.105	GARAGE JCM	DIVERS ELEC
			PLAQUETTES AV RPLT
13/05/2025	59.837	GARAGE JCM	CAPTEURS DIVERS RPLT
15/11/2024	54.100	AUTO D.M.C	DIVERS CLIM
			REVISION
			FILTRE A AIR RPLT
			LIQUIDE DE FREIN
			FILTRE CLIM RPLT
			REVISION
			RECYCLAGE
19/02/2024	36.435	FRANCE PARE BRISE SAS	CUSTODE ARG RPLT
02/02/2024	35.524	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
26/01/2024	35.456	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
17/03/2023	20.209	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE
12/12/2022	16.646	SARL DEHEEGHER	LIQUIDE DE FREIN
			REVISION
			FILTRE CLIM RPLT
21/03/2022	7.777	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE
23/09/2021	1.783	NORAUTO SAS (PRODUIT SPE)	REPARATION DE ROUE