

# Seat

VIN: VSSZZKJXPR106743

Estimated repair cost

621.43 EUR  
TOTAL



## Description

Registration number	Registration date	Odometer
-	-	76373 km
Color	Year	Upholstery
-	-	-
Number of doors	Number of seats	Generation
-	-	-

## Vehicle Equipments

Cruise control	Automatic headlights	Electrically foldable door mirrors
Climate control	Park Assist	Alloy wheel rims
Rear sensors	Front sensors	SATNAV
Xenon headlights		

## Active warning lights

Tyre pressure indicator







## Statement details

Inspection loc	Statement date	Inspection approval date
PARC GENERAL LEASE	10/02/2026	11/02/2026

## Control

Engine start issue	Is not roadworthy
No	No

## Defects & corrections

#	Element	Defect	Correction	net cost
001	Tyre pressure indicator	Defective	Check	0.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum -
	Bodywork cost	Paint cost	MaterialCost	
002	Interior complete / -	Stained	Cleaning	0.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum -
	Bodywork cost	Paint cost	MaterialCost	
003	Carpet / Front Left	Burn mark	Smart repair	53.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum <b>53.00 EUR</b>
	Bodywork cost	Paint cost	MaterialCost	
004	Floor mat / Interior Front Left	Burn mark	Acceptable	-
	Bodywork time	Paint time	Part Price	Lumpsum -
	Bodywork cost	Paint cost	MaterialCost	
005	Full aerial / -	Missing	Replace	83.28 EUR
	Bodywork time <b>1.00 h</b>	Paint time	Part Price <b>23.28 EUR</b>	Lumpsum -
	Bodywork cost <b>60.00 EUR</b>	Paint cost	MaterialCost	
006	Wing extension moulding / Front Left Painted : No	Scratched	Replace	61.63 EUR
	Bodywork time <b>0.60 h</b>	Paint time	Part Price <b>25.63 EUR</b>	Lumpsum -
	Bodywork cost <b>36.00 EUR</b>	Paint cost	MaterialCost	
007	Bumper / Front <sup>1</sup> Painted : Yes	Scratched	Smart repair	78.00 EUR

	Bodywork time	Paint time	Part Price	Lumpsum <b>78.00 EUR</b>
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	
	-	-	-	
008 Rim / Front Left Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted				
	Scratched	Acceptable		-
	Bodywork time	Paint time	Part Price	Lumpsum -
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	
	-	-	-	
009 Tailgate / Boot door / Back <sup>2</sup>				
	Dent	Smart repair		40.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum <b>40.00 EUR</b>
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	
	-	-	-	
010 Rear parcel shelf / -				
	Missing	Replace		88.45 EUR
	Bodywork time	Paint time	Part Price	Lumpsum -
	<b>0.20 h</b>	-	<b>76.45 EUR</b>	
	Bodywork cost	Paint cost	MaterialCost	
	<b>12.00 EUR</b>	-	-	
011 Bumper / Back Painted : Yes				
	Scratched	Polishing		29.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum <b>29.00 EUR</b>
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	
	-	-	-	
012 Door sill / Interior Back Right				
	Dent	Smart repair		40.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum <b>40.00 EUR</b>
	-	-	-	
	Bodywork cost	Paint cost	MaterialCost	
	-	-	-	
013 Door / Front Right				
	Dent	Acceptable		-

	Bodywork time	Paint time	Part Price	Lumpsum	
	-	-	-		
	Bodywork cost	Paint cost	MaterialCost	-	
	-	-	-		
014	Wing extension moulding / Front Right Painted : No		Scratched	Replace	61.63 EUR
	Bodywork time	Paint time	Part Price	Lumpsum	
	<b>0.60 h</b>	-	<b>25.63 EUR</b>		
	Bodywork cost	Paint cost	MaterialCost	-	
	<b>36.00 EUR</b>	-	-		
015	Bumper extension moulding / Front Right Painted : No		Scratched	Replace	46.44 EUR
	Bodywork time	Paint time	Part Price	Lumpsum	
	<b>0.60 h</b>	-	<b>10.44 EUR</b>		
	Bodywork cost	Paint cost	MaterialCost	-	
	<b>36.00 EUR</b>	-	-		
016	Door / Back Left		Dent	Smart repair	40.00 EUR
	Bodywork time	Paint time	Part Price	Lumpsum	
	-	-	-		
	Bodywork cost	Paint cost	MaterialCost	<b>40.00 EUR</b>	
	-	-	-		

<sup>1</sup> Ovb, herstelling

<sup>2</sup> X2

## Loose Items

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Rear parcel shelf          | <input type="checkbox"/> Remote key               | <input checked="" type="checkbox"/> Tyre repair kit complete |
| <input type="checkbox"/> Security Kit               | <input type="checkbox"/> Cabrio wind deflector    | <input type="checkbox"/> Cabrio wind deflector bag           |
| <input type="checkbox"/> Compressor tyre repair kit | <input type="checkbox"/> Document holder          | <input checked="" type="checkbox"/> Triangle                 |
| <input type="checkbox"/> DVD screen                 | <input checked="" type="checkbox"/> First aid kit | <input type="checkbox"/> Warranty booklet                    |
| <input type="checkbox"/> User manual                | <input type="checkbox"/> Memory card              | <input type="checkbox"/> Toolkit                             |
| <input type="checkbox"/> Fragrance diffuser         | <input type="checkbox"/> Hook /Hicth ball         | <input type="checkbox"/> Jack                                |
| <input type="checkbox"/> Jack handle crank          | <input type="checkbox"/> Card key                 | <input type="checkbox"/> Load cover                          |
| <input type="checkbox"/> Slow charging cable        | <input type="checkbox"/> Mechanical key           | <input type="checkbox"/> Refill tyre repair kit              |
| <input type="checkbox"/> Charging cable bag         | <input type="checkbox"/> Conformity certificate   | <input checked="" type="checkbox"/> Spare Key                |
| <input type="checkbox"/> Spare wheel tyre           | <input type="checkbox"/> Separation net           | <input type="checkbox"/> Service book                        |
| <input type="checkbox"/> Quick charging cable       | <input type="checkbox"/> In-car tools             | <input type="checkbox"/> Towing hook                         |
| <input checked="" type="checkbox"/> Safety vest     | <input type="checkbox"/> Divider bar of the bag   | <input type="checkbox"/> Locking wheel nut                   |
| <input type="checkbox"/> Cargo net                  |   |  |

## Main set of tyres

---

<b>Front Left</b>	MICHELIN	205 / 60 / 16 / All	3 mm
<b>Front Right</b>	MICHELIN	205 / 60 / 16 / All	3 mm
<b>Back Left</b>	HANKOOK	205 / 60 / 16 / All	4.5 mm
<b>Back Right</b>	HANKOOK	205 / 60 / 16 / All	4.5 mm

## Comments

---

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer








Navigation



Spare Tyre



Vin





Floor mat / Interior Front Left / Burn mark



Full aerial / - / Missing



Full aerial / - / Missing




Wing extension moulding / Front Left / Scratched




Wing extension moulding / Front Left / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Rim / Front Left / Scratched



Tailgate / Boot door / Back / Dent



Tailgate / Boot door / Back / Dent



Tailgate / Boot door / Back / Dent



Rear parcel shelf / - / Missing



Rear parcel shelf / - / Missing



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched




Door sill / Interior Back Right / Dent



Door sill / Interior Back Right / Dent



Door sill / Interior Back Right / Dent



Door / Front Right / Dent



Wing extension moulding / Front Right / Scratched



Wing extension moulding / Front Right / Scratched



Bumper extension moulding / Front Right / Scratched



Bumper extension moulding / Front Right / Scratched



Door / Back Left / Dent



Door / Back Left / Dent