MACADAM









OPEL CORSA: GJ-667-GE

Vinnumber:	**VXKUBYHTKN4329084**	Versionname:	**OPEL CORSA 1.5 Diesel 100ch Edition VP [5P] bvm 6-102CH-5cv (bi-corps)**
First Registrationdate:	**5/09/2022**	Fiscalpower:	
Expertise Mileage:	**123536**	Power Kw:	**75**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Luggage cover	
Windows electric F		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

	195/55/16/87 H			
Winter tyres:	Fr.L.	**Goodyear: 45%**	Fr.R.	**Goodyear: 80%**
	Re.L.	**Goodyear: 45%**	Re.R.	**Goodyear: 45%**

Tyre profile depth FL	**5.4**
Tyre profile depth FR	**3.1**
Tyre profile depth RL	**5.2**
Tyre profile depth RR	**5.2**
Tyre size FL	**195/55 R 16 87 H**
Tyre size FR	**195/55 R 16 87 H**
Tyre size RL	**195/55 R 16 87 H**
Tyre size RR	**195/55 R 16 87 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning







Tyre FL, Out of tolerance, Replace




Alloy rim FL, Scratch(es), Repair/replace (lump sum)




Tyre RL, Out of tolerance, Replace




Tyre RR, Out of tolerance, Replace




Tyre FR, Out of tolerance, Replace




Wing RL, Scratch(es), Acceptable




Bumper F, Scratch(es), Paint




Bonnet, Dent(s), Acceptable




Wing RR, Dent(s), Repair and paint (complete)




Outer sill R, Scratch(es), Paint




ALPHABET

Historique Maintenance

Immatriculation: **GJ-667-GE** Date de 1ère immatriculation: **05/09/2022**

Modèle: **Opel CORSA 1.5 Diesel 100ch Edition VP [5P] bvm 6-102CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
25/08/2026	120.734	SOCIETE CHAVOT	Huile
			BALAIS ESSUIE GLACE AV AR
			REVISION ET CLIM ET AIR ET CARBURANT
			Pieces
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			Main D'œuvre
			DISQUES PLAQUETTES AV RPLT
			LIQUIDE DE FREIN
			ADBLUE
			COURROIE ACCESSOIRES RPLT
20/11/2025	101.704	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
13/05/2025	86.028	SOCIETE CHAVOT	PILE DE CLE RPLT
			REVISION ET CLIM ET AIR ET CARBURANT
			ADBLUE
11/04/2025	84.002	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
02/12/2024	62.004	FLEET SOLUTIONS FRANCE	PERMUTATIONS PNEUS
			REMPLACEMENT PNEUS HIVER
28/08/2024	51.572	STELLANTIS &YOU FRANCE SAS	BALAIS ESSUIE GLACE AV AR
			REVISION ET CLIM
			LIQUIDE DE FREIN
19/12/2023	23.357	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER
15/12/2023	22.584	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS HIVER
13/10/2023	15.464	STELLANTIS &YOU FRANCE SAS	REVISION ET CLIM

Historique Maintenance

Immatriculation: **GJ-667-GE** Date de 1ère immatriculation: **05/09/2022**

Modèle: **Opel CORSA 1.5 Diesel 100ch Edition VP [5P] bvm 6-102CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
			BALAIS ESSUIE GLACE AV AR