

Condition Report

DEKRA/AAGI041/20260322

Ordered By

Ordered By Budget Magyarország

Vehicle

License Plate		Contract Number		Bodywork Type	Estate car	Transmission	6 gear mechanic
Brand	KIA	VIN	U5YH4819ANL135127	Drive Wheel	Front-wheel-drive	First Registration	2022.11.18
Model	Ceed	Year Built	2022	Color	White	Fuel Type	Hybrid
Label	-	Capacity	1.598 cm3	Power	100 kW	Mileage	174.574 km
MOT	2026.11.18						

Equipment

- Automatic air conditioning / digital
- Electrically adjustable front and rear windows
- Multifunction steering wheel
- ESP / DSC
- ASD / EDS / ASR

Documents

- Original Key
- Registration Book
- Vehicle Manual
- Spare tire

Wheels

Position	Rim Type	Dimensions	Thread Depth
FL	Acél	195/65R15	4.00
FR	Acél	195/65R15	4.00
RL	Acél	195/65R15	4.00
RR	Acél	195/65R15	4.00
SP	Acél	125/80R15	3.00


Paint Thickness [µm]

Part	Left Value	Right Value
Front mudguard	125	203
Engine cover	210	0
Front door	306	283
Rear door	123	186
Roof	117	0
Rear mudguard	117	213
Luggage compartment lid / Rear door	108	0

Last Service

Type	Date	KM
------	------	----

Standard Images





Special Notes

A gépjármű a szemle időpontjában szennyezett volt. A hibák ill. az esetleges jégkár csak korlátozottan észlelhetők.

This condition report was prepared by an expert of DEKRA-Expert Kft.

The vehicle inspection was carried out by external visual examination. No test drive was performed and no parts were disassembled during the inspection.

The calculation of unacceptable defects and deficiencies was prepared using data from the Audatex and Eurotax calculation programs.

The expert inspection was carried out in accordance with DEKRA regulations, applying the client's guidelines regarding acceptable and unacceptable defects and deficiencies for returned vehicles.