TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Service-Center
Aalen-Essingen
Margarete-Steiff-Str. 7
73457 Aalen-Essingen

Besichtigungsdatum:	14.10.2026
Protokollnummer:	**48285782**
Erstellt durch:	Markus Böttcher
Besichtigt durch:	Schittenhelm

NLHDR51D1SZ367128

Angaben zum Fahrzeug

Halter		**Besichtigungszustand**	ausreichend
Kennzeichen		**Laufleistung (abgelesen)**	24.479 km
Hersteller	Hyundai	**Restlauf bis Service**	226 Tag(e)
Typ/Modell	i10	**HU (abgelesen aus ZBI)**	10/2028
Fahrgestellnummer	NLHDR51D1SZ367128	**Leistung**	66 kW
Hubraum	998 ccm	**Zylinder**	3
Erstzulassung	07.10.2025	**Polster/Farbe**	Stoff / Schwarz-Rot
Letzte Wartung		**Lackierung**	Schwarz
Kraftstoffart	Benzin	**Getriebe**	Manuell

Zustandsbericht

Wertmindernde Faktoren

Nr.	Bauteilgruppe	Beschreibung
1	Fahrzeugdach	Antennenstab - Marderschaden - erneuern
2	Stossfänger hinten	Stossfänger hinten (Ladekante) - Kratzer - Smart Repair

Gebrauchsspuren

Nr.	Bauteilgruppe	Beschreibung
Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.		

Fehlteile

Fehlteil

Festgestellte Nachlackierungen

Nr.	Ort
Keine feststellbar	

Hauptbereifung

Achse	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Verktgl.	Zul.
1	195/45 R16 84H	Hankook	Sommerreifen	6mm - 6mm	i.O.	i.O.
2	195/45 R16 84H	Hankook	Sommerreifen	6mm - 6mm	i.O.	i.O.

Ersatz

Typ	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Ablaufdatum
Tirefit					12/2030

Der Verschleißzustand sowie evtl. Schäden an der Bereifung sind wertmäßig berücksichtigt.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Service-Center
Aalen-Essingen
Margarete-Steiff-Str. 7
73457 Aalen-Essingen

Besichtigungsdatum:	14.10.2026
Protokollnummer:	**48285782**
Erstellt durch:	Markus Böttcher
Besichtigt durch:	Schittenhelm

Angaben zum Fahrzeug

Hersteller	Hyundai	**Besichtigungszustand**	ausreichend
Typ/Modell	i10	**Laufleistung (abgelesen)**	24.479 km
Fahrgestellnummer	NLHDR51D1SZ367128	**Erstzulassung**	07.10.2025

Angaben zum Auftrag:
Auftragsgemäß erfolgte die Fahrzeugzustandsbewertung in demontagefreien Zustand.

Grundlage dieses Produktes stellt der Leitfaden für Fahrzeugrücknahmen und Bewertungen gemäß des Schadengrenzmusterkatalog des Auftraggebers dar. Die expliziten Feststellungen im Einzelfall trifft der Sachverständige objektiv im Rahmen der vorgegebenen Standards aufgrund eigener Sachkunde.

Fahrzeug-Identifizierung:
Die Fahrzeug-Identifizierungsnummer (FIN) wurde am Fahrzeug abgelesen und die Übereinstimmung im Verlauf der Besichtigung durch den Unterzeichner mit den vorgelegten Unterlagen festgestellt.

Besichtigungsbedingungen:
Die Besichtigungsbedingungen waren zur Beurteilung des Fahrzeuges ausreichend.

Allgemeinzustand:
Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.



Unterschrift Sachverständiger (Markus Böttcher)

Vorliegendes Druckexemplar wurde auf elektronischem Wege erzeugt. Der benannte Sachverständige versichert, dass der Inhalt die von ihm getroffenen Feststellungen korrekt wiedergibt. Es ist ohne Originalunterschrift gültig.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig


Besichtigungsort
TÜV SÜD Service-Center
Aalen-Essingen
Margarete-Steiff-Str. 7
73457 Aalen-Essingen

Besichtigungsdatum:	14.10.2026
Protokollnummer:	**48285782**
Erstellt durch:	Markus Böttcher
Besichtigt durch:	Schittenhelm

Übersichtsfotos



Abbildung 1: FIN


Abbildung 2: Schräg vorne



Abbildung 3: Schräg vorne



Abbildung 4: Schräg hinten




Abbildung 5: Schräg hinten


Abbildung 6: Montierte Bereifung




Abbildung 7: Innenraum vorne



Abbildung 8: Laderaum



Abbildung 9: Kombiinstrument



Abbildung 10: Kombiinstrument



Abbildung 11: Instrumententafel



Abbildung 12: Dokumente



Abbildung 13: Dokumente

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Service-Center
Aalen-Essingen
Margarete-Steiff-Str. 7
73457 Aalen-Essingen

Besichtigungsdatum:	14.10.2026
Protokollnummer:	**48285782**
Erstellt durch:	Markus Böttcher
Besichtigt durch:	Schittenhelm

Beschädigungsfotos



Beschädigung #1: Fahrzeugdach: Antennenstab - Marderschaden - erneuern



Beschädigung #1: Fahrzeugdach: Antennenstab - Marderschaden - erneuern



Beschädigung #2: Stossfänger hinten: Stossfänger hinten (Ladekante) - Kratzer - Smart Repair



Beschädigung #2: Stossfänger hinten: Stossfänger hinten (Ladekante) - Kratzer - Smart Repair

HYUNDAI

COMPLETE VEHICLES
CERTIFICATE OF CONFORMITY

Übereinstimmungsbescheinigung
Πιστοποιητικό Συμμόρφωσης
Certificat de Conformité
Certificate of Conformity
Certificato di Conformità
Conformiteitscertificaat
Świadectwo Zgodności
Certifikat o skladnosti
Certificado de Conformidad

046CC0190332
www PS-Team de

Part 1

The undersigned — I. K. OH, GENERAL MANAGER

hereby certifies that the vehicle:

0.1. Make (Trade name of manufacturer): Hyundai
0.2. Type: AC3
- Variant: A5P51
- Version: M55B11

0.2.1. Commercial name(s): i10
0.2.2.1. Allowed Parameter Values for multistage type approval to use the base vehicle emission values
Final Vehicle actual mass : -
Final Vehicle technically permissible maximum laden mass (in kg) : -
Frontal area for final vehicle (in cm²) : -
Rolling resistance (kg/t) : -
Cross-sectional area of air entrance of the front grille (in cm²) : -
0.2.3. Identifiers
0.2.3.1. Interpolation family's identifier: IP-050630-NLH
0.2.3.2. ATCT family's identifier: AT-050007-NLH
0.2.3.3. PEMS family's identifier: 05-HAO-19-1
0.2.3.4. Roadload family's identifier: RL-050007-NLH
0.2.3.5. Roadload Matrix family's identifier: -
0.2.3.6. Periodic regeneration family's identifier: -
0.2.3.7. Evaporative test family's identifier: EV-010001-NLH
0.4. Vehicle category: M1
0.5. Company name and address of manufacturer:
HYUNDAI ASSAN OTOMOTIV San.Ve.Tic. A.S.Aydinevler Mah.Sanayi Cad 32 IcKapi 20 Maltepe Istanb./Turkey
0.6. Location and method of attachment of the statutory plates:
On the left hand B-post, bonded
Location of the vehicle identification number:
Under the right front seat
0.9. Name and address of the manufacturer's representative:
Hyundai Motor Europe Technical Center GmbH; Hyundai Platz, 65428 Rüsselsheim, Germany

0.10. Vehicle identification number: NLHDR51D1SZ367128

0.11. Date of manufacture of the vehicle: 21.04.2025
conforms in all respects to the type described in approval
approval e5*2007/46*0090*09
issued on 08.03.2024
and can be permanently registered in Member States having right hand traffic and using metric units for the speedometer and metric units for the odometer

Place , Date and Signature: HMC — Issue Date 14.05.2025

Part 2

General construction characteristics

1. Number of axles: 2 and wheels 4
3. Powered axles (number, position, interconnection): 1, Front
3.1. Specify if the vehicle is non-automated/automated/fully automated: non-automated

Main dimensions

4. Wheelbase: 2425 mm
4.1. Axle spacing: 1-2: 2425 mm 2-3: mm 3-4: mm
5. Length: 3675 mm
6. Width: 1680 mm
7. Height: 1483 mm

Masses

13. Mass in running order: 1099 kg
13.2. Actual mass of the vehicle: 1111 kg
16. Technically permissible maximum masses
16.1. Technically permissible maximum laden mass: 1470 kg

: 1. 785 kg 2. 730 kg
the combination: 1780 kg
mass in case of:
- kg
310 kg
16.4. Unbraked trailer: 310 kg
19. Technically permissible maximum static vertical mass at the coupling point: 75 kg

Power plant

20. Manufacturer of the engine: Hyundai or Kia
21. Engine code as marked on the engine: G3LE
22. Working principle: Positive ignition / 4-stroke
23. Pure electric: no
23.1. Class of Hybrid [electric] vehicle: no
24. Number and arrangement of cylinders: 3; Inline
25. Engine capacity: 998 cm3
26. Fuel: Gasoline
26.1. Mono fuel/Bi fuel/Flex fuel/Dual-fuel: Mono fuel
26.2. (Dual-fuel only)
27. Maximum power
27.1. Maximum net power: 66,20 kW at 5500min-1 (internal combustion engine) :
27.3. Maximum net power: - kW (electric motor)
27.4. Maximum 30 minutes power: - kW (electric motor)

28. Gearbox (type): Manual
28.1. Gearbox ratios

1st gear	2nd gear	3rd gear	4th gear	5th gear	6th gear	7th gear	8th gear
3.615	1.955	1.207	0.893	0.688	-	-	-

28.1.1. Final drive ratio: -
28.1.2. Final drive ratios

1st gear	2nd gear	3rd gear	4th gear	5th gear	6th gear	7th gear	8th gear
3.647	3.647	3.647	3.647	3.647	-	-	-

Maximum speed

29. Maximum speed: 175 km/h

Axles and suspension

30. Axle(s) track: 1. 1467 mm 2. 1478 mm
35. Fitted tyre/wheel combination/energy efficiency class of rolling resistance coefficients (RRC) and tyre category used for CO2 determination:
Axle1 : 195/45R16 84H 6.5JX16/ET48 / B/C1
Axle2 : 195/45R16 84H 6.5JX16/ET48 / B/C1

HM315490

5481761

Brakes

36. Trailer brake connections -

Bodywork

38. Code for bodywork: AB(hatchback)
40. Colour of vehicle: black
41. Number and configuration of doors: 5; 2 left, 2 right, 1 rear
42. Number of seating positions (including the driver): 5
42.1. Seat(s) designated for use only when the vehicle is stationary: -
42.3. Number of wheelchair user accessible position: -

Environmental performances

46. Sound level
- Stationary: 78,30 dB(A) at engine speed : 3750 min-1
- Drive-by: 70,00 dB(A)

47. Exhaust emission level: Euro 6 EA
47.1. Parameters for emission testing of Vind
47.1.1. Test mass, kg: 1194
47.1.2. Frontal area, m2: 2.147
47.1.2.1. Projected frontal area of air entrance of the front grille, cm2: -
47.1.3. Road load coefficients
47.1.3.0. f0, N: 87.7
47.1.3.1. f1, N/(km/h): 0.592
47.1.3.2. f2, N/(km/h) 2: 0.0318
47.2. Driving cycle
47.2.1. Driving Cycle class: 3b
47.2.2. Downscaling factor (fdsc): -
47.2.3. Capped speed: no
48. Exhaust emissions:
EC715/2007*2023/443EA

1.2. Test procedure: Type I (WLTP highest values) or WHSC (EURO VI)

CO:	83,9 mg/km
THC:	8,3 mg/km
NMHC :	6.2 mg/km
NOx:	10,4 mg/km
THC+NOx:	- mg/km
NH3 :	-
Particulates (mass) :	0,150 mg/km
Particles (number) :	0.98E + 11

2.2. test procedure: WHTC (EURO VI)

CO:	- mg/km
NOx:	- mg/km
NMHC :	- mg/km
THC :	- mg/km
CH4 :	- mg/km
CH3 :	- mg/km
Particulates (mass) :	- mg/km
Particles (number) :	-

48.1. Smoke corrected absorption coefficient: -(m-1)

48.2. Declared maximum RDE values

	Complete RDE trip:	Urban RDE trip:
NOx:	60mg/km	60 mg/km
Particles (number) :	6E+11	6E+11

49. CO2 emissions/fuel consumption/electric energy consumption:

1. All power trains, except OVC electric vehicles

WLTP values	CO2 emissions	Fuel consumption	Electric consumption (ECAC)
Low:	155 g/km	6.8 l/100 km	- Wh/km
Medium:	118 g/km	5.2 l/100 km	- Wh/km
High:	104 g/km	4.6 l/100 km	- Wh/km
Extra High	131 g/km	5.8 l/100 km	- Wh/km
Combined:	123 g/km	5.4 l/100 km	- Wh/km

2. Electric range of pure electric vehicles

Electric range	- km
Electric range city	- km

3. Vehicle fitted with eco-innovation(s): -

3.1. General code of the -

3.2. Total CO2 emissions savings due to the eco-innovation(s)

3.2.2. WLTP savings: - g/km

4. OVC hybrid electric vehicles

WLTP values	Charge Sustaining		Electric consumption
	CO2 emissions	Fuel consumption	(EC)
Low :	- g/km	- l/100 km	- Wh/km
Medium :	- g/km	- l/100 km	- Wh/km
High :	- g/km	- l/100 km	- Wh/km
Extra High :	- g/km	- l/100 km	- Wh/km
City :			- Wh/km
Combined :	- g/km	- l/100 km	- Wh/km

WLTP values	Charge depleting	
	CO2 emissions	Fuel consumption
Combined :	- g/km	- l/100 km

Weighted	CO2 emissions	Fuel consumption	Electric consumption (ECAC)
Combined Value:	- g/km	- l/100 km	- Wh/km

5. Electric range of OVC hybrid electric vehicles (if applicable)

Equivalent All Electric Range (EAER)	- km
Equivalent All Electric Range city (EAER city)	- km
All Electric Range (AER) :	- km
All Electric Range city (AER city) :	- km

Miscellaneous

51. For special purpose vehicles: designation in accordance with point 5 of Part A of Annex I to Regulation (EU) 2018/858 of the European Parliament and of the Council:
52. Remarks:
13:1099*27.1:66.20/4500-5500*35:195/45R16 84H,LM-Rad 6.5Jx16 /ET48*

54. Vehicle fitted with:
TPMS/ELKS/AEBS/ESS/AIF/ISA/DDAW/EDR/eCALL

55. Vehicle Certified in accordance with UN Regulation No.155: YES

56. Vehicle Certified in accordance with UN Regulation No.156: YES