VEHICLE REPORT

IT · 11/11/2026
2026-11-11 10:16

VIN: Targa: Merchant:

VEHICLE DETAILS

Targa		First Registration	**2015-04-01**
Marca	N/A	Mileage	N/A
Modello e Allestimento		Keys	N/A
VIN		Owners	**2**
Merchant		Seats	**5**
Branch		Previous Use	**AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE**
KW	**184**	VAT	N/A
CC	**0**	Country	**IT**
Fuel	**GASOL**	Euro	**EURO6**
GPL	**Non presente**	Cambio	**AUTOMATICO**
Gancio	N/A		

CAR PHOTOS (59)


Roof


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Center console and dashboard


Center console and dashboard


Speedometer with started engine.


Speedometer with started engine


Front door left


Interior front


Interior rear


Interior front


Interior rear


Trunk


Front door left


Trunk


Trunk


Interior rear


Front door left


Interior front


Interior front


Left side front


Left side front


Rear fender left


Left side front


Rear fender left


Left side front


Rear fender left


Left side front


Left side front


Left side front



Left side front



Front right



Left side rear



Left side front



Right side front



Left side front



Right side rear



Rear



Rear



Rear



Right side rear



Roof.



Roof



Additional photos (optional)



Front left



Front left



Front



Engine compartment



Engine compartment



Engine compartment



Engine compartment



Engine compartment



Interior front.

CARFAX **Vehicle History Report**

2015 PORSCHE CAYENNE

Vehicle reference:
WP1ZZZ92ZFLA41035

Body type:
Estate

Engine size:
2967 cm³

Total system power:
184 kW / 250 hp

Combustion engine power:
184 kW / 250 hp

Gearbox type:
Automatic

Fuel type:
Diesel

Quick check

Damage
No damage reported to CARFAX

Import
Not a private import

Legend

- No issues reported or indicated
- Valuable Information
- Requires attention
- Data unavailable

Damage overview

No issues reported

Our data shows **no damage or accident records** for this vehicle.

Keep in mind
CARFAX only reflects information that's been reported to us.

While having no reported damage is a positive sign, it's still important to take a close look at the vehicle during your test-drive:



- Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.
- Don't hesitate to ask the seller for additional details or service documentation.

Recommended maintenance

Default schedule
Provided by CARFAX Europe



Vehicle age
11 years, 7 months

Maintenance due so far

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:
- Are service records available?
- Were the following services performed?

Engine oil and oil filter **due 11 times**
Change every year

Brake fluid **due 5 times**
Change every 2 years

Diesel fuel filter **due 5 times**
Change every 2 years

Costly upcoming service tasks

Before buying, confirm whether:
- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

Brake discs and pads
Inspect yearly, replace as needed

Tires
Inspect yearly, replace as needed

CARFAX tips



Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.

Mileage Check

No issues reported

According to the data provided to CARFAX, there are no indications of odometer manipulation.

Last odometer reading

122 063 km


Reported on: 2023-04-03

Today's mileage projection

For this vehicle

~171 330 km

Date	Mileage projection
2026-11-11	~171 330 km



CARFAX tips



Mileage can have a significant impact on a vehicle's value.

Consider whether the mileage matches what you'd expect for the vehicle. Look for signs of wear, compare the readings with typical yearly averages.

Owners BETA



Owner(s) in Italy

Purchase year:
2015

There is no more information available about one or more consecutive owners.

Owner(s) in Italy

Purchase year:
2020

There is no more information available about one or more consecutive owners.

Technical details

Engine and performance

Fuel type
Diesel

Combustion engine power
184 kW / 250 hp

Environment and consumption

CO2 emissions in mixed driving
173 g/km 

Fuel consumption in mixed driving
6.6 l/100km

EU emission standard
Euro 6

Weight

Curb weight
2 185 kg

Max payload
685 kg

Gross vehicle weight
2 870 kg

Dimensions

Length
4 855 mm

Width
1 939 mm

Wheelbase
2 895 mm

Other information

European vehicle category
M1

EU standard code
e13*2007/46*1085*11

Number of doors
5

Number of seats
5

History information

Date	Mileage	Event
2015-04-01		**Registered in Italy**
2019-04-16	66 890 km	**Inspected in Italy**
2020-03-20		**New owner reported**
2021-04-14	95 188 km	**Inspected in Italy** Inspection type: regular Inspection passed
2023-04-03	122 063 km	**Inspected in Italy** Inspection type: regular Inspection valid until 2025-04-03

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our Terms and conditions.