MACADAM








Volkswagen Polo (UKL): 2BWX032

Vinnumber:	**WVWZZZAWZNU032677**	Versionname:	**Polo Life 1.0TSi 95pk/cv 5p**
First Registrationdate:	**25/04/2022**	Fiscalpower:	
Expertise Mileage:	**82421**	Power Kw:	**70**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 5 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**+ 28400 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**185/65/15/92 T**			
	Fr.L.	**Fulda: 5 mm**	Fr.R.	**Fulda: 6 mm**
	Re.L.	**Hankook: 6 mm**	Re.R.	**Hankook: 6 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**185/65 R 15 92 T**
Tyre size FR	**185/65 R 15 92 T**
Tyre size RL	**185/65 R 15 92 T**
Tyre size RR	**185/65 R 15 92 T**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2484**
Tyre make FR	**2484**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Door RL, Dent(s) and scratch(es), Repair and paint (complete)






Door FL, Dent(s) and scratch(es), Acceptable








Tailgate / Boot, Scratch(es), Acceptable







Bumper R, Scratch(es), Repair and paint (complete)





Door FR, Scratch(es), Repair and paint (complete)






Wing RR, Scratch(es), Acceptable




Roof, Scratch(es), Repair and paint (complete)





Onderhoudshistorie van: WVWZZZAWZNU032677

ALPHABET

Kenteken	2BWX032
Merk Model	Volkswagen Polo Life 1.0TSi 95pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	4/25/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/25/26	87,451	bougie	Vervangen
9/25/26	87,451	Inspectie met olieververvanging (vast in	Uitvoeren
9/25/26	87,451	klein materiaal	
9/25/26	87,451	luchtfilter	Vervangen
9/25/26	87,451	luchtfilter interieur	Vervangen
9/25/26	87,451	remvloeistof	Vervangen
9/25/26	87,451	ruitenwisserrubber achter	Vervangen
9/25/26	87,451	ruitenwisserrubber vooraan	Vervangen
5/15/25	55,796	bougie	Vervangen
5/15/25	55,796	Inspectie met olieververvanging (vast in	Uitvoeren
5/15/25	55,796	klein materiaal	
5/15/25	55,796	remblokken vooraan	Vervangen
5/15/25	55,796	ruitenwisserrubber vooraan	Vervangen
5/15/25	55,796	ruitenwisservloeistof	Bijvullen/-laden
3/24/25	53,032	controle niveaus	Uitvoeren
3/24/25	53,032	olie bijvullen	Bijvullen/-laden
3/24/25	53,032	ruitenwisservloeistof	Bijvullen/-laden
2/5/25	50,198	diagnose	Uitvoeren
8/8/24	41,348	controle niveaus	Uitvoeren
8/8/24	41,348	olie bijvullen	Bijvullen/-laden
8/8/24	41,348	ruitenwisservloeistof	Bijvullen/-laden
6/21/24	38,738	diagnose	Uitvoeren
6/21/24	38,738	klein materiaal	Uitvoeren
2/2/24	28,977	Inspectie met olieververvanging (vast in	Uitvoeren
2/2/24	28,977	klein materiaal	Uitvoeren
2/2/24	28,977	luchtfilter interieur	Vervangen
2/2/24	28,977	remvloeistof	Vervangen
2/2/24	28,977	ruitenwisserrubber achter	Vervangen
2/2/24	28,977	ruitenwisserrubber vooraan	Vervangen
2/2/24	28,977	ruitenwisservloeistof	Bijvullen/-laden