MACADAM








MINI (UKL): 2FNQ355

Vinnumber:	**WMW31DK0502W05387**	Versionname:	**Cooper (F55) 1.5i 136pk/cv 5p Aut.**
First Registrationdate:	**26/06/2024**	Fiscalpower:	
Expertise Mileage:	**63961**	Power Kw:	**100**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**plus 31000 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**195/55/16/87 H**			
	Fr.L.	**Goodyear: 4 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Hankook: 4 mm**	Re.R.	**Hankook: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**195/55 R 16 87 H**
Tyre size FR	**195/55 R 16 87 H**
Tyre size RL	**195/55 R 16 87 W**
Tyre size RR	**195/55 R 16 87 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Door panel RR, Scratch(es), Acceptable




Bumper spoiler F, Scratch(es), Replace





Bonnet, Hail damage, Repair and paint (complete)














Door FL, Dent(s) and scratch(es), Acceptable






Wing RL, Dent(s) and scratch(es), Acceptable






Luggage compartment cover, Missing, Replace



Bumper R, Scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




Bodywork, Not original part, Remove lettering




Fuel cap cover, Scratch(es), Acceptable





Roof, Hail damage, Repair and paint (complete)









Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WMW31DK0502W05387

ALPHABET

Kenteken	2FNQ355
Merk Model	MINI Cooper (F55) 1.5i 136pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	6/26/24

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/21/26	62,848	BMW/MINI service standaard omvang	Uitvoeren
9/21/26	62,848	klein materiaal	
9/21/26	62,848	remschijven en blokken achter	Vervangen
9/21/26	62,848	ruitenwisserrubber achter	Vervangen
9/21/26	62,848	ruitenwisserrubber vooraan	Vervangen
9/11/26	62,419	batterij	Vervangen
9/11/26	62,419	BMW/MINI service standaard omvang	Uitvoeren
9/11/26	62,419	BMW/MINI service voertuig-check	Uitvoeren
9/11/26	62,419	bougie	Vervangen
9/11/26	62,419	brandblusapparaat	Vervangen
9/11/26	62,419	klein materiaal	
9/11/26	62,419	ruitenwisservloeistof	Bijvullen/-laden
9/11/26	62,419	service luchtfilter	Uitvoeren
9/11/26	62,419	service microfilter	Uitvoeren
9/11/26	62,419	service motorolie	Uitvoeren
12/3/25	37,610	BMW/MINI service standaard omvang	Uitvoeren
12/3/25	37,610	klein materiaal	
12/3/25	37,610	remblokken vooraan	Vervangen
8/26/25	30,306	BMW/MINI service standaard omvang	Uitvoeren
8/26/25	30,306	controle niveaus	Uitvoeren
8/26/25	30,306	klein materiaal	
8/26/25	30,306	service microfilter	Uitvoeren
8/26/25	30,306	service motorolie	Uitvoeren