



## HYUNDAI TUCSON: GC-978-FS

|                         |                          |                         |                                                                                            |
|-------------------------|--------------------------|-------------------------|--------------------------------------------------------------------------------------------|
| Vinnumber:              | <b>TMAJC81AGMJ116221</b> | Versionname:            | <b>HYUNDAI TUCSON 1.6 CRDI 136 DCT-7 HYBRID 48V BUSINESS VP [5P] bva 7-136CH-7cv (SUV)</b> |
| First Registrationdate: | <b>6/10/2021</b>         | Fiscalpower:            |                                                                                            |
| Expertise Mileage:      | <b>168228</b>            | Power Kw:               | <b>100</b>                                                                                 |
| Bodytype:               | <b>SUV</b>               | Body colour:            | <b>Blue</b>                                                                                |
| Gearbox:                | <b>Automatic</b>         | Paint type:             | <b>Metallic</b>                                                                            |
| Transmission:           | <b>Front</b>             | Interior colour:        | <b>Black</b>                                                                               |
| Fueltype:               | <b>Diesel</b>            | Type of rims (mounted): | <b>Aluminium</b>                                                                           |
| Engine functioning:     | <b>Yes</b>               | Dashboard color:        | <b>Black</b>                                                                               |
| Battery functioning:    | <b>Yes</b>               |                         |                                                                                            |
| Vehicle running:        | <b>Yes</b>               |                         |                                                                                            |
| Number of doors:        | <b>5</b>                 |                         |                                                                                            |
| Number of seats:        | <b>5</b>                 |                         |                                                                                            |
| Number head rests:      | <b>5</b>                 |                         |                                                                                            |
| Type of rims (mounted): | <b>Aluminium</b>         |                         |                                                                                            |
| Category:               | <b>Passenger Car</b>     |                         |                                                                                            |

## Options

|                                |                              |                            |                     |
|--------------------------------|------------------------------|----------------------------|---------------------|
| Number of keys total           | <b>2</b>                     | Tow bar                    |                     |
| Number keys remote             | <b>2</b>                     | Radio                      |                     |
| GPS big screen color           |                              | Central consol F           |                     |
| Windows electric F             |                              | Luggage cover              |                     |
| Cruise Control                 |                              | Headlights Xenon/LED/Laser |                     |
| Steering wheel multifunctional |                              | Front parking sensors      |                     |
| Steering wheel leather         |                              | Rear parking sensors       |                     |
| Type of climate control        | <b>Autom climate control</b> | Rear view camera           |                     |
|                                |                              | Seat cover lining          | <b>Lining Other</b> |

## Tyres

| 215/65/17/103 V       |       |               |       |                   |
|-----------------------|-------|---------------|-------|-------------------|
| Summer tyres:         | Fr.L. | Michelin: 20% | Fr.R. | Michelin: 20%     |
|                       | Re.L. | Michelin: 20% | Re.R. | Michelin: 20%     |
| Tyre profile depth FL |       |               |       | 6.9               |
| Tyre profile depth FR |       |               |       | 7.0               |
| Tyre profile depth RL |       |               |       | 7.0               |
| Tyre profile depth RR |       |               |       | 7.0               |
| Tyre size FL          |       |               |       | 215/65 R 17 103 V |
| Tyre size FR          |       |               |       | 215/65 R 17 103 V |
| Tyre size RL          |       |               |       | 215/65 R 17 103 V |
| Tyre size RR          |       |               |       | 215/65 R 17 103 V |
| Tyre type FL          |       |               |       | Summer            |
| Tyre type FR          |       |               |       | Summer            |
| Tyre type RL          |       |               |       | Summer            |
| Tyre type RR          |       |               |       | Summer            |
| Tyre make FL          |       |               |       | 261               |
| Tyre make FR          |       |               |       | 261               |
| Tyre make RL          |       |               |       | 261               |
| Tyre make RR          |       |               |       | 261               |

## Assistance equipment

Seat cover FL, Stain, Cleaning



Seat cover FR, Stain, Cleaning



Door RL, Scratch(es), Paint



Wing FL, Scratch(es), Acceptable



Bumper F, Scratch(es), Paint



Door RR, Dent(s), Repair and paint (complete)



Wing FR, Scratch(es), Polish



Historique Maintenance

Immatriculation: GC-978-FS Date de 1ère immatriculation: 06/10/2021

Modèle: Hyundai TUCSON 1.6 CRDI 136 DCT-7 HYBRID 48V BUSINESS VP [5P] bva 7-136CH-7cv (SUV)

| Date       | Kilométrage | Fournisseur            | Descriptif                           |
|------------|-------------|------------------------|--------------------------------------|
| 19/12/2025 | 142.920     | FLEET SOLUTIONS FRANCE | REPLACEMENT PNEUS HIVER              |
| 10/10/2025 | 134.464     | DEKRA AUTOMOTIVE S.A   | CONTROLE TECHNIQUE                   |
| 04/10/2024 | 94.597      | BAYARD AUTOMOBILE      | PLAQUETTES AV RPLT                   |
|            | 0           |                        | REVISION                             |
|            | 0           |                        | PLAQUETTES AR RPLT                   |
|            | 0           |                        | LIQUIDE DE FREIN                     |
| 12/10/2023 | 64.016      | KOREAN MOTORS CAR      | LIQUIDE DE FREIN                     |
|            | 0           |                        | BALAISSUIE GLACE AV AR               |
|            | 0           |                        | REVISION ET CLIM ET AIR ET CARBURANT |
| 20/06/2023 | 62.624      | CONTITRADE FRANCE      | REPLACEMENT PNEUS ETE                |
| 15/12/2022 | 36.145      | KOREAN MOTORS CAR      | REVISION ET CLIM                     |
|            | 0           |                        | LIQUIDE DE FREIN                     |