MACADAM










Opel Crossland: P105KL

Vinnumber:	**W0V7D9EB8N4183753**	Versionname:	**Crossland 1.2 Turbo 96kW S/S GS Line automaat**
First Registrationdate:	**7/04/2022**	Fiscalpower:	
Expertise Mileage:	**137322**	Power Kw:	**96**
Bodytype:		Body colour	**White Jade (S)**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**852**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**1**	Rear parking sensors	
GPS		Hook	
Autom climate control		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 50 / 17 / 95 / H / Aluminium	5,0 mm	Bridgestone	Summer
	Right	215 / 50 / 17 / 95 / H / Aluminium	5,0 mm	Bridgestone	Summer
Rear	Left	215 / 50 / 17 / 95 / H / Aluminium	4,5 mm	Bridgestone	Summer
	Right	215 / 50 / 17 / 95 / H / Aluminium	4,5 mm	Bridgestone	Summer

Assistance equipment

Door FL, Scratch(es), Repair and paint (complete)





Wing RL, Scratch(es), Polish




Bonnet, Dent(s), Repair and paint (complete)




Windscreen, Stone chip(s), Windscreen repair







Bumper moulding R, Scratch(es), Replace




Ignition key, Missing, Replace

No pictures to display

Onderhoudshistorie van: W0V7D9EB8N4183753

ALPHABET

Kenteken	P105KL
Merk Model	Opel Crossland 1.2 Turbo 96kW S/S GS Line automaat
Brandstofsoort	Benzine
Datum deel1	4/7/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
7/27/26	132,365	Vervanging band
6/3/26	128,550	Bougie
6/3/26	128,550	Luchtfilter
6/3/26	128,550	Onderhoudsbeurt
6/3/26	128,550	Remvloeistof
3/24/26	121,524	APK
7/29/25	105,372	Onderhoudsbeurt
7/29/25	105,372	Riem/ multiriem
7/29/25	105,372	Sleutelbatterij
6/6/25	102,570	Reparatie band(en)
10/25/24	84,754	Distributie riem
10/25/24	84,754	Onderhoudsbeurt
10/25/24	84,754	Remblokken achterzijde
10/25/24	84,754	Remschijf + blokken voor
10/25/24	84,754	Startmotor
10/25/24	84,754	Vervanging band
10/25/24	84,754	Vliegwiel
5/3/24	70,501	Remklauw(en) voorzijde
2/16/24	62,700	Onderhoudsbeurt
2/16/24	62,700	Remvloeistof
6/9/23	43,583	Onderhoudsbeurt
6/9/23	43,583	Sleutelbatterij
12/13/22	26,835	Reparatie band(en)
10/14/22	21,333	Onderhoudsbeurt