DS DS 7 CROSSBACK

Vehicle information

Make:	**DS**	License:	**2BUR328**
Gearbox:		Body color:	
Model:	**DS 7 CROSSBACK**	VIN:	**VR1J4DGZUNY521619**
Fuel type:		Power:	**133 kW**
Version:	**1.6 PHEV 225 RIVOLI AUTO**	First registration	**29/03/2022**
Mileage:	**136949 km**	N° of doors:	

Damage summary

Front	1
Left	2
Rear	2
Right	2
Roof & others	2

Commercial pictures




























Options according to the inspector

GPS	**Yes**

Tyres

Front Left

All season

235/50/19/103/W

Vredestein

2.0 mm

Front Right

All season

235/50/19/103/W

Vredestein

2.0 mm

Rear Left

All season

235/50/19/103/W

Bridgestone

6.0 mm

Rear Right

All season

235/50/19/103/W

Bridgestone

6.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Maintenance	**OK**
Number of charging cables (normal)	**1**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**No**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Statutory inspection	**OK**
Statutory inspection	**29/03/2028**	Type of Maintenance book	**Maintenance book present**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.