MACADAM









Volkswagen Polo: G833KS

Vinnumber:	**WVWZZZAWZLU016192**	Versionname:	**Polo 1.0 TSI 85kW Comfortline Business**
First Registrationdate:	**25/10/2019**	Fiscalpower:	
Expertise Mileage:	**65814**	Power Kw:	**85**
Bodytype:		Body colour	**Pure White**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Petrol**	Parking lot	**353**
Number of seats	**5**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS			
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	185 / 65 / 15 / 92 / T / Steel	7,4 mm	Continental	Winter
	Right	185 / 65 / 15 / 92 / T / Steel	7,4 mm	Continental	Winter
Rear	Left	185 / 65 / 15 / 92 / T / Steel	7,8 mm	Continental	Winter
	Right	185 / 65 / 15 / 92 / T / Steel	7,8 mm	Continental	Winter

Assistance equipment

Roof liner, Stain, Cleaning




Interior, Stain, Cleaning






Wing RL, Scratch(es), Repair and paint (complete)




Bonnet, Stone chip(s), Repair and paint (complete)




Bumper F, Dent(s), Repair and paint (complete)





Wing FR, Dent(s), Repair and paint (complete)





Door RR, Dent(s), Repair and paint (complete)





Bumper R, Scratch(es), Repair and paint (complete)





Onderhoudshistorie van: WVWZZZAWZLU016192

ALPHABET

Kenteken	G833KS
Merk Model	Volkswagen Polo 1.0 TSI 85kW Comfortline Business
Brandstofsoort	Benzine
Datum deel1	10/25/19

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/20/26	65,812	Onderhoudsbeurt
10/20/26	65,812	Remblokken achterzijde
10/20/26	65,812	Remblokken voorzijde
11/6/25	54,959	APK
11/6/25	54,959	Luchtfilter
11/6/25	54,959	Onderhoudsbeurt
11/6/25	54,959	Remvloeistof
11/6/25	54,959	Vervanging band
11/4/24	45,388	Accu
11/13/23	38,539	Bougie
11/13/23	38,539	Onderhoudsbeurt
10/13/23	38,004	APK
10/13/23	38,004	Uitlijnen voor en achterwielen
10/13/23	38,004	Vervanging band
11/9/21	21,930	Onderhoudsbeurt
10/29/19	15	Band(en)