



AUDI A3:

Vinnumber:	WAUZZZGYXNA004746	Versionname:	
First Registrationdate:	23/08/2021	Fiscalpower:	
Expertise Mileage:	68773	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2807
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	over 17200 km		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

205/55/16/91 V			
Summer tyres:	Fr.L.	Nexen: 3 mm	Fr.R.
	Re.L.	Nexen: 3 mm	Re.R.
Tyre profile depth FL			3.0
Tyre profile depth FR			3.0
Tyre profile depth RL			3.0
Tyre profile depth RR			3.0
Tyre size FL			205/55 R 16 91 V
Tyre size FR			205/55 R 16 91 V
Tyre size RL			205/55 R 16 91 V
Tyre size RR			205/55 R 16 91 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			1957072
Tyre make FR			1957072
Tyre make RL			1957072
Tyre make RR			1957072

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	202,64
Engine insulation, Tear, Replace	69,61



Windscreen, Stone chip(s), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Bumper moulding F, Scratch(es), Acceptable

0,00



Wing RL, Repaired, Acceptable

0,00



Door RL, Repaired, Acceptable

0,00



Door RL, Dent(s), Acceptable

0,00



Alloy rim FL, Scratch(es), Acceptable

0,00



Step L, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

133,03



Bumper R, Scratch(es), Acceptable

0,00



Rear spoiler, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Acceptable

0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00



Roof, Scratch(es), Acceptable

0,00



