MACADAM








BMW 3 Reeks (KKL): 2CKT115

Vinnumber:	**WBA81CE080FN36540**	Versionname:	**316d Touring (G21) 2.0d 122pk/cv 5p Aut.**
First Registrationdate:	**29/08/2022**	Fiscalpower:	
Expertise Mileage:	**93450**	Power Kw:	**90**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Diesel**		
Maintenance	**NOT OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/50/17/98 Y**			
	Fr.L.	**Bridgestone: 3 mm**	Fr.R.	**Bridgestone: 3 mm**
	Re.L.	**Bridgestone: 3 mm**	Re.R.	**Bridgestone: 3 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**225/50 R 17 98 Y**
Tyre size FR	**225/50 R 17 98 Y**
Tyre size RL	**225/50 R 17 98 Y**
Tyre size RR	**225/50 R 17 98 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Service, Maintenance, Check



Alloy rim RL, Scratch(es), Repair and paint (complete)







Door RL, Dent(s) and scratch(es), Acceptable






Door FL, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)






Bumper R, Scratch(es), Repair and paint (complete)







Door RR, Scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)





Bodywork, Paint measurement, Acceptable




Bodywork, Not original part, Remove lettering



Onderhoudshistorie van: WBA81CE080FN36540

ALPHABET

Kenteken	2CKT115
Merk Model	BMW 316d Touring (G21) 2.0d 122pk/cv 5p Aut.
Brandstofsoort	Diesel
Datum deel1	8/29/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/7/25	70,415	batterij	Vervangen
8/7/25	70,415	BMW/MINI service standaard omvang	Uitvoeren
8/7/25	70,415	klein materiaal	
8/7/25	70,415	remvloeistof	Vervangen
8/7/25	70,415	ruitenwisserrubber achter	Vervangen
8/7/25	70,415	ruitenwisserrubber vooraan	Vervangen
8/7/25	70,415	ruitenwisservloeistof	Bijvullen/-laden
8/7/25	70,415	service brandstoffilter	Uitvoeren
8/7/25	70,415	service microfilter	Uitvoeren
8/7/25	70,415	service motorolie	Uitvoeren
7/11/24	46,648	BMW/MINI service standaard omvang	Uitvoeren
7/11/24	46,648	BMW/MINI service voertuig-check	Uitvoeren
7/11/24	46,648	klein materiaal	
7/11/24	46,648	remblokken achter	Vervangen
7/11/24	46,648	ruitenwisserrubber achter	Vervangen
7/11/24	46,648	ruitenwisserrubber vooraan	Vervangen
7/11/24	46,648	service luchtfilter	Uitvoeren
7/11/24	46,648	service microfilter	Uitvoeren
7/11/24	46,648	service motorolie	Uitvoeren
8/31/23	20,695	batterij	Vervangen
8/31/23	20,695	BMW/MINI service standaard omvang	Uitvoeren
8/31/23	20,695	klein materiaal	Uitvoeren
8/31/23	20,695	service microfilter	Uitvoeren
8/31/23	20,695	service motorolie	Uitvoeren