



VSSZZZKM4RR057567

Angaben zum Fahrzeug

Halter		Besichtigungszustand	ausreichend
Kennzeichen		Laufleistung (abgelesen)	43.066 km
Hersteller	CUPRA	Restlauf bis Service	12.800 km
Typ/Modell	FORMENTOR	HU (Abgelesen aus ZBI)	05/2027
Fahrgestellnummer	VSSZZZKM4RR057567	Leistung / Hubraum	110 kW / 1.498 ccm
Erstzulassung	22.05.2024	Polster/Farbe	Stoff/Leder Kombination / Schwarz-Anthrazit
Letzte Wartung	09/2025, 28.184 km	Lackierung	Schwarz
Kraftstoffart	Benzin	Getriebe	Automatik

Zustandsbericht

Gebrauchsspuren

Nr.	Bauteilgruppe	Beschreibung
1	Verglasung	Frontscheibe (Oberflächensteinschläge) - Steinschlag - kein Abzug
2	Motorhaube	Motorhaube - Steinschlag - kein Abzug
3	Stoßfänger hinten	Spoiler - Kratzer - kein Abzug

Fehlteile

Fehlteil

Festgestellte Nachlackierungen

Nr.	Ort
Keine feststellbar	

Hauptbereifung

Achse	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Verktgl.	Zul.
1	245/45 R18 96W	Continental	Sommerreifen	6mm - 6mm	i.O.	i.O.
2	245/45 R18 96W	Continental	Sommerreifen	5mm - 5mm	i.O.	i.O.

Ersatz

Typ	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Ablaufdatum
Notrad	125/70 R18 99M	Sonstige	Sommerreifen	4	

Der Verschleißzustand sowie evtl. Schäden an der Bereifung sind wertmäßig berücksichtigt.

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Besichtigungsort
MVI Oberschleißheim
Mittenheimer Straße 64
85764 Oberschleißheim

Besichtigungsdatum: 14.07.2026
Protokollnummer: 46506838
Erstellt durch: Paula Kube
Besichtigt durch: Milorad Kojic



Angaben zum Fahrzeug

Hersteller	CUPRA	Besichtigungszustand	ausreichend
Typ/Modell	FORMENTOR	Laufleistung (abgelesen)	43.066 km
Fahrgestellnummer	VSSZZZKM4RR057567	Erstzulassung	22.05.2024

Angaben zum Auftrag:

Auftragsgemäß erfolgte die Fahrzeugzustandsbewertung in demontagefreien Zustand.

Grundlage dieses Produktes stellt der Leitfaden für Fahrzeugrücknahmen und Bewertungen gemäß des Schadengrenzmusterkatalog des Auftraggebers dar. Die expliziten Feststellungen im Einzelfall trifft der Sachverständige objektiv im Rahmen der vorgegebenen Standards aufgrund eigener Sachkunde.

Fahrzeug-Identifizierung:

Die Fahrzeug-Identifizierungsnummer (FIN) wurde am Fahrzeug abgelesen und die Übereinstimmung im Verlauf der Besichtigung durch den Unterzeichner mit den vorgelegten Unterlagen festgestellt.

Besichtigungsbedingungen:

Die Besichtigungsbedingungen waren zur Beurteilung des Fahrzeuges ausreichend.

Allgemeinzustand:

Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.

Unterschrift Sachverständiger (Paula Kube)

Vorliegendes Druckexemplar wurde auf elektronischem Wege erzeugt. Der benannte Sachverständige versichert, dass der Inhalt die von ihm getroffenen Feststellungen korrekt wiedergibt. Es ist ohne Originalunterschrift gültig.

Übersichtsfotos



Abbildung 1: FIN



Abbildung 2: Schräg vorne



Abbildung 3: Schräg vorne



Abbildung 4: Schräg hinten



Abbildung 5: Schräg hinten



Abbildung 6: Montierte Bereifung




Abbildung 7: Innenraum vorne



Abbildung 8: Laderaum



Abbildung 9: Laderaum



Abbildung 10: Kombiinstrument




Abbildung 11: Kombiinstrument



Abbildung 12: Instrumententafel

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Besichtigungsort
MVI Oberschleißheim
Mittenheimer Straße 64
85764 Oberschleißheim

Besichtigungsdatum: 14.07.2026
Protokollnummer: 46506838
Erstellt durch: Paula Kube
Besichtigt durch: Milorad Kojic




Abbildung 13: Instrumententafel




Abbildung 14: Dokumente




Abbildung 15: Dokumente

046CC0170722



www.PS-Team.de



Certificate of Conformity

Complete vehicles

The undersigned hereby certify that the vehicle:

0.1.	Make (Trade name of manufacturer):	CUPRA
0.2.	Type:	Variant:
	KM	CXDPCA00
0.2.1.	Commercial name:	FORMENTOR
0.2.2.1.	Allowed Parameter Values for multistage type approval to use the base vehicle emission values	
	Final Vehicle actual mass [kg]:	
	Final Vehicle technically permissible maximum laden mass[kg]:	
	Frontal area for final vehicle [cm2]:	
	Rolling resistance [kg/t]:	
	Cross-sectional area of air entrance of the front grille [cm2]:	
0.2.3.1.	Interpolation family's identifier:	IP-MQB37WZ_A0_0577-VSS-1
0.2.3.2.	ATCT family's identifier:	AT-5Q0_0V_0255_000-VSS-1
0.2.3.3.	PEMS family's identifier:	09-VSS-716W_KM_DPCA_FD7_A-000
0.2.3.4.	Roadload family's identifier:	RL-DQ381_7F_19_001-WWW-1
0.2.3.5.	Roadload matrix family's identifier (if applicable):	
0.2.3.6.	Periodic regeneration family's identifier:	PR-VW_00221_00_000-WWW-1
0.2.3.7.	Evaporative test family's identifier:	EV-AU_DGW_D_AVAAB-WWW-1
0.4.	Vehicle category:	M1
0.5.	Company name and address of manufacturer:	SEAT, S.A., Autovía A-2, Km. 585, ES-08760 Martorell
0.6.	Location and method of attachment of the statutory plates:	
	On the right A-pillar, glued or bonded	
	Location of the vehicle identification number:	
	In the engine compartment, right	
0.9.	Name and address of the manufacturer's representative:	
0.10.	Vehicle identification number:	VSSZZZKM4RR057567
0.11.	Date of manufacture of the vehicle:	2023-12-16

conforms in all respects to the type described in approval e9*2007/46*4008*19 granted on 2023-10-20 and can be permanently registered in Member States having right hand traffic and using metric units for the speedometer and metric units for the odometer.

Martorell, 2023-12-16

Martorell, 2023-12-16

Daniel Cortina Munuera

Director Quality Assurance

Robin Christoph Bräutigam

Head of Technical Conformity

Internal Manufacturer's data

VSSZZZKM4RR057567



CoC Version: 1

51. For special purpose vehicles: Designation in accordance with CR (CE) 2018/858 annex I part A point 5:

52. Remarks:

NO 16.2.: with trailer axle 2+15 kg##NO 35.: alt. to pos 35 with deviating val.

in pos 49: 245/40 R19 94VW#8,0JX19 ET40;##245/45 R18 96VW#8,0JX18 ET40;##215/55 R

17 94V M+S#7,5JX17 ET40;##225/50 R18 95V M+S#8,0JX18 ET40;##225/55 R17 97V M+S#7

,5JX17 ET40;##

54. Vehicle fitted with advanced vehicle systems:

eCall, ESS, TPMS

55. Vehicle certified in accordance with UN-R No 155:

no

56. Vehicle certified in accordance with UN-R No 156:

no

1

Number of axles / wheels:

2 / 4

3

Powered axles (number, position):

1, Axle 1

3.1

Interconnection of powered axles:

4

Wheelbase[mm]:

2679

4.1

Axle spacing [mm]:

2679

5

Length [mm]:

4450

6

Width [mm]:

1839

7

Height [mm]:

1528

13

Mass in running order [kg]:

1458

13.2

Actual mass of the vehicle [kg]:

1513

16

Technically permissible maximum masses:

16.1

Technically permissible maximum laden mass [kg]:

1980

16.2

Technically permissible mass on each axle (1./2.) [kg]:

1020 / 1010

16.4

Technically permissible maximum mass of the combination [kg]:

3480

18

Technically permissible maximum towable mass in case of:

18.1

Drawbar trailer [kg]:

18.3

Centre-axle trailer [kg]:

1500

18.4

Unbraked trailer [kg]:

720

19

Technically permissible maximum static vertical mass at the coupling point [kg]:

80

20

Manufacturer of the engine:

Volkswagen AG

21

Engine code as marked on the engine:1

ADPC

22

Working principle:

Positive ignition / 4 stroke

23

Pure electric:

no

23.1

Class of Hybrid (electric) vehicle:

24

Number and arrangement of cylinders:1

4; in Line

25

Engine capacity [cm³]:

1498

26

Fuel:

petrol

26.1

Mono fuel/Bi fuel/Flex fuel/Dual fuel:

mono fuel vehicle

26.2

Type of dual fuel engine:

27

Maximum power

27.1

Maximum net power [kW at min⁻¹] (internal combustion engine):

110.00 / 5000

27.3

Maximum net power [kW] (electric motor):

27.4

Maximum 30 minutes power [kW] (electric motor):

28

Gearbox (type):

automatic

28.1

Gear

28.1.2

Gearbox ratios:

28.1.2

Final drive ratio:

29

Maximum speed [km/h]:

203

30

Axle(s) track (1./2.) [mm]:

1585 / 1559

35

Fitted tyre/wheel combination/energyefficiency class of RRC/type category used for CO₂ determination:

35

Axle 1:

245/45 R18 96W / 8.0JX18 ET40 / A / C1

35

Axle 2:

245/45 R18 96W / 8.0JX18 ET40 / A / C1

36

Trailer brake connections:

38

Code for bodywork:

AC

40

Colour of vehicle:

BLACK

41

Number and configuration of doors:

5 / le. 2, ri. 2, ba. 1

42

Number of seating positions (including the driver):

5

42.1

Seat(s) designated for use only when the vehicle is stationary:

42.3

Number of wheelchair user accessible position:

46

Sound level

46

Stationary [dB(A) at min⁻¹]:

75.10 / 3750

46

Drive-by [dB(A)]:

65.00

47

Exhaust emission level:

EURO 6 AP

47.1

Parameters for emission testing of V_{ind}:

47.1.1

Test mass [kg]:

1593

47.1.2

Frontal area [m²]:

47.1.3

Road load coefficients

47.1.3.0. f0 [N]	47.1.3.1. f1 [N/(km/h)]	47.1.3.2. f2: [N/(km/h)²]
108.1	0.252	0.03881

47.2

Driving cycle:

47.2.1

Driving cycle class:

3b

47.2.2

Downscaling factor (f_{ds}):

47.2.3

Capped speed:

no

48

Exhaust emissions:

715/2007*2018/1832AP

1.2

Test procedure: Type 1 (WLTP highest values) [mg/km] or WHSC (EURO VI) [mg/kWh]

Petrol / Diesel	CO	THC	NMHC	NO _x	THC + NO _x	NH ₃ [ppm]	Particulates	Particles #
	380.6	30.6	26.5	14.2	---	---	0.9800	0.32E11
LPG/CNG	---	---	---	---	---	---	---	---
Other	---	---	---	---	---	---	---	---

2.2

Test procedure: WHTC (EURO VI) [mg/kWh]

Petrol / Diesel	CO	THC	NMHC	CH ₄	NO _x	NH ₃	Particulates	Particles #
	---	---	---	---	---	---	---	---
LPG/CNG	---	---	---	---	---	---	---	---
Other	---	---	---	---	---	---	---	---

48.1

Smoke corrected absorption coefficient [m⁻¹]:

48.2

Declared maximum RDE values (if applicable):

NO _x [mg/km]	Particulates (number) with exponent (#/km)
60.0	6.00 E11
60.0	6.00 E11

48.2

Complete RDE trip:

48.2

Urban RDE trip:

MOBILITY CONCEPT

LVV Nr 6140511
Hersteller Cupra
Model Formentor
Variante DE - SUV5 1.5 TSI EU6d, 2020 - 2024 1.5 TSI
Listenpreis 37.777,34
VIN VSSZZZKM4RR057567
Erstzulassungsdatum 22.5.2024
Kennzeichen M-TJ 1431

Schadensfälle der int. Belegnummer: 6140511 22.07.2026

Schadennummer	Unfalldatum	Beschädigung	Schadenhöhe in EUR
2025100822	19.01.2025	Windschutzscheibe gerissen	918,59
2026110886	12.07.2026	Windschutzscheibe gerissen	