

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia						
				Policyholder				Opposite party				Opposite party company				
				Operation 2026		Claim number			Code / Agency				Date accident 16/07/2026			
				Expert code		Adjuster code			Policy number				Injured person can recover the VAT			
Date assignment 16/07/2026		Date first survey 04/08/2026		Place Pordenone		C/O	Repairs		Photo	Lien in favor of			Expiry date			
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate				
Lessee / Co-owner												Date of overhaul				
Vehicle (Brand - Model - Version) VOLKSWAGEN PASSAT Var. 2.0TDI SCR EVO 110kW Business DSG								Plate GK139ZG		Vin Chassis WVWZZZ3CZNE077673				First Registration 05/07/2022		
Usage status NON CONOSCIUTO		Km 121704	Tyres % 90		Color Blu		Type of enamel METALLIZED/DOUBLE			Consistency of damage		Type of Expert's report NOT DEFINITIVE				
Equipment																
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase	Seats No. 0	Axles 0									
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses										
Damaged items / restoration operations								SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)
								Dif	Time	Dif	Time	Dif	Time	Time		
1	3G0857537JGRU	External rear-view mirror cap				L	S		S		S					
1	3G1857508FJ9B9	External electrically adjustable rear-view mirror				R	S		S		S					
1	3G0845011CGNVB	Windshield					S		S		S					
1	D169300M1	Window glueing kit					S		S		S					
1	3G0853665K9B9	Front bumper side grille				L	S		S		S					
1	3G0821021B	Front mudguard				L	L				L					
1	3G0831055AG	Front door				L	L				L					
1	3G9809843	rear mudguard				L	L		L		L					
1	3G9807417MGRU	Rear bumper					L		L		L					
1	3G9809844	rear mudguard				R	L		M		L					
1	3G9833056AE	Rear door				R	L		M		M					
1	3G0807217APGRU	Front bumper					L		L		L					
1	3G0853331BGRU	Trim of front door				L	L				L					
1	Codice Ricambio	Cerchio post. - Rettifica				R										
1	Codice Ricambio	Cerchio ant. - Rettifica				R										
1	Codice Ricambio	Cerchio ant. - PRM				L										

New for old value (N)	Remarks Pneum. Fulda 215/55 R17. Vhl sporco.
-----------------------	--