



Land Rover Range Rover Velar: S863HS

Vinnnumber:	SALYA2BY1PA355769	Versionname:	Range Rover Velar 2.0 P400E PHEV 297kW 4WD Aut
First Registrationdate:	31/01/2023	Fiscalpower:	
Expertise Mileage:	73968	Power Kw:	221
Bodytype:		Body colour:	Santorini Black - metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	523
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 50 / 20 / 109 / W / Aluminium	5,5 mm	Goodyear	Summer
	Right	255 / 50 / 20 / 109 / W / Aluminium	5,3 mm	Goodyear	Summer
Rear	Left	255 / 50 / 20 / 109 / W / Aluminium	5,5 mm	Goodyear	Summer
	Right	255 / 50 / 20 / 109 / W / Aluminium	5,2 mm	Goodyear	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Side window trim RL, Scratch(es), Polish



Side window trim FL, Scratch(es), Polish



Outside rear-view mirror housing L, Scratch(es), Polish




Bonnet, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Shutter / cover R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper corner RL, Scratch(es), Polish



Kenteken	S863HS
Merk Model	Land Rover Range Rover Velar 2.0 P400E PHEV 297kW 4WD Aut
Brandstofsoort	Benzine
Datum deel1	31-01-23

Datum reparatie	Kilometerstand	Reparatie omschrijving
09-08-24	37.898	Onderhoudsbeurt
09-08-24	37.898	Remvloeistof