



Volkswagen ID.4 BEV 204pk 77kWh 1st Max, Dec-20, 110,502 km



Memo





VIN	WVGZZZE2ZMP006768
Initial registration	22-12-2020
Initial Dutch Registration	22-12-2020
European Type Approval	e1*2018/858*00004*01
Mileage reading / hour counter reading	110,502 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	2024 kg
Doors	5
Power capacity	150 kW
Emission code / Energy label	Z
Wheelbase	277
Loading space	
Load capacity	
RDW details	
Battery capacity	77 kWh
Range	380 km
Battery health	
Charging cables type	2
AC/DC	ACDC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Gray
Country of registration	The Netherlands
Origin	Lease

Accessories fitted to vehicles

	Tailgate electrically operated		Electronic Stability Program		Parking sensors rear
	Rear view camera		Electric windows front		Parking sensors front + rear
	Adaptive cruise control		Electric windows front + rear		Start immobiliser
	Adaptive power steering		Electric operated seats		Fold away towbar
	ABS		LED lighting		Heated windscreen
	Automatic air conditioning ECC		Alloy rims		Heated front seats
	Automatic interior mirror dimmer		Metallic paint		Heat reflecting glass
	Bluetooth telephone connection		Navigation		
	Central locking remote control		Panorama roof		

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|--|---|--|
| <ul style="list-style-type: none"> • Achteropk verkeer waarsch • Adap. damping syst. • AEB • Afwijk. dakkleur • Apple Carpl./Android Auto • Armsteun achter • Armsteun voor • Bagage-scheidingsnet • Band.sp.contr.syst. • Bestuurdersairbag • Bluetooth telefoonvoorb. • Buitensp. elekt. inklapb. • Buitensp. elektr. + verw. • Centrale airbag v. • Connected services • Cruise contr.adap Stop&Go • DAB radio • Dakrails • Dodehoek detectie • Draadloze telefoonlader • Elek. achterklep met sens • ESP | <ul style="list-style-type: none"> • Extra getint glas • File assistent • Forward Collision Warning • Geluidsisolerend glas • Grootlichtassistent • Head-up display • Hill hold functie • Hoofd airbag(s) a. • Hoofd airbag(s) v. • In delen neerkl. achterb. • Interieur voorverwarming • Keyless entry • Keyless start • LED achterlichten • LED dagrijverlichting • Lederen stuurwiel • Lendesteunen (verstelb.) • Lichtmetalen velgen 21" • Matrix LED koplampen • Multifunctioneel stuur • Multimedia scherm middel • Multimedia-voorbereiding | <ul style="list-style-type: none"> • Navigatiesysteem • Oplaadmogelijkheid • Panoramadak • Passagiersairbag • Rijstrooksensor met corr. • Rondomzicht camera • Ruitensproeiers verwarmb. • Spraakbediening • Stoel best. hoogte verst. • Stoel pass. hoogte verst. • Stof/kunstlederen bekl. • Stuurwiel verwarmd • Var. stuuroverbrenging • Verkeersbord detectie • Vermoeidheids herkenning • Verstelbaar stuur • Verwarmde voorruit • Voorstoel(en) met massage • WiFi voorbereiding • Zij airbag(s) v. |
|--|---|--|





Comments

No remarks

Vehicle state					
MOT due date	22-12-2026	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location	Wheel locks	Not present
			Owner		
					

Tyres			
Rim size	21"		
Wheel	Brand	Type	Tread depth
Front wheel left	Pirelli	Summer tyre	6 mm
Front wheel right	Pirelli	Summer tyre	4 mm
Rear wheel left	Pirelli	Summer tyre	3 mm
Rear wheel right	Pirelli	Summer tyre	3 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection				
Incident		Component	Observations	
Unacceptable damage				
2		Wheel rim left-front	scratch(es)	
3		Wielkuip bekleding v l	scratch(es)	
4		Front door left	scratch(es)	
5		Rear wing left	dent(s)	
6		Rear door left	scratch(es)	
7		Bumper v l hoek	scratch(es)	
8		Engine bonnet	Hail damage	



9



Front screen

crack

10



Wheel rim right-front

scratch(es)

11



Rear right rim

scratch(es)



12



Kofferklep

scratch(es)

Comments

No remarks

Vendor