MACADAM







Peugeot Rifter: 2BCS983

Vinnumber:	**VR3ERHNP2MN540493**	Versionname:	**Rifter Standard Allure 1.2 PureTech S/S 110pk/cv 5p**
First Registrationdate:	**4/10/2021**	Fiscalpower:	
Expertise Mileage:	**109579**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar fixed**
Type of Maintenance book	**Maintenance book present**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/16/102 H**			
	Fr.L.	**Michelin: 2 mm**	Fr.R.	**Michelin: 2 mm**
	Re.L.	**Michelin: 4 mm**	Re.R.	**Michelin: 4 mm**

Tyre profile depth FL	**2.0**
Tyre profile depth FR	**2.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/65 R 16 102 H**
Tyre size FR	**215/65 R 16 102 H**
Tyre size RL	**215/65 R 16 102 H**
Tyre size RR	**215/65 R 16 102 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Interior, Damaged, Acceptable




Seat cover FL, Stain, Cleaning



Bumper moulding F, Scratch(es), Replace and paint




Door FL, Dent(s) and scratch(es), Acceptable






Door RL, Scratch(es), Acceptable




Compressor, Missing, Check



Tyre repair kit, Missing, Check



Tailgate / Boot, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Smart repair




Outside rear-view mirror housing R, Scratch(es), Acceptable




Wheel cover FR, Scratch(es), Replace




Onderhoudshistorie van: VR3ERHNP2MN540493

ALPHABET

Kenteken	2BCS983
Merk Model	Peugeot Rifter Standard Allure 1.2 PureTech S/S 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	10/4/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/5/26	108,149	halogeenlamp	Vervangen
10/5/26	108,149	oliezeef	Vervangen
10/5/26	108,149	remblokken vooraan	Vervangen
8/13/26	103,388	olie bijvullen	Bijvullen/-laden
5/11/26	96,727	controle niveaus	Uitvoeren
5/11/26	96,727	olie bijvullen	Bijvullen/-laden
1/23/26	90,426	olie bijvullen	Bijvullen/-laden
11/4/25	85,198	halogeenlamp	Vervangen
11/4/25	85,198	luchtfilter	Vervangen
11/4/25	85,198	luchtfilter interieur	Vervangen
11/4/25	85,198	oliezeef	Vervangen
8/14/25	80,298	olie bijvullen	Bijvullen/-laden
5/26/25	74,451	bougie	Vervangen
5/26/25	74,451	distributieriem	Vervangen
5/26/25	74,451	luchtfilter	Vervangen
4/25/25	71,708	olie bijvullen	Bijvullen/-laden
2/6/25	67,060	halogeenlamp	Vervangen
11/21/24	61,493	olie bijvullen	Bijvullen/-laden
11/21/24	61,493	oliezeef	Vervangen
11/21/24	61,493	onderhoud 12 maand	Uitvoeren
11/21/24	61,493	remvloeistof	Vervangen
8/21/24	56,266	halogeenlamp	Vervangen
5/10/24	51,439	olie bijvullen	Bijvullen/-laden
12/6/23	42,381	luchtfilter interieur	Vervangen
12/6/23	42,381	olie bijvullen	Bijvullen/-laden
12/6/23	42,381	oliezeef	Vervangen
12/6/23	42,381	onderhoud 12 maand	Uitvoeren
1/15/23	21,930	controle niveaus	Uitvoeren
8/24/22	14,027	oliezeef	Vervangen
8/24/22	14,027	onderhoud 12 maand	Uitvoeren