

2-FGV-182



2-FGV-182 · FR 1,0L TSI 110HP DSG KJ75RZ E05 · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FGV-182	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ9RR122614
Model	Arona	Cylinder Capacity	999 ^{cm3}
Model Versions	FR 1,0L TSI 110HP DSG KJ75RZ E05	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	06-05-2024
Color	Blue	Odometer	74.412 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	85	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	5 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	4 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	5 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Dashboard



Damage Type

Small scratch(es)

Repair Type

Spotrepair

Acceptable

No



Damage Part

Interior



Damage Type


Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Alloy - Right Rear



Damage Type

Damaged

Repair Type

Acceptable

Acceptable

Yes



Damage Part
Reardoor – Left



Damage Type
Small dent(s)

Repair Type	Acceptable
Restyle	No



Damage Part
Bumper – Rear



Damage Type
Scratch(es)

Repair Type	Acceptable
Spray	No



Damage Part
Tailgate



Damage Type
Small dent(s)

Repair Type	Acceptable
Restyle	No