



Expertise

Protocol number: 46736459
Order No. / Reference: 26742071
Inspection date: 27 Jul 2026

Manufacturer: Volkswagen

Model: ID.4 4Motion Pro Infotainment-Paket "Plus"

VIN: WVGZZZE2ZPE073910



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen ID.4 4Motion Pro Infotainment-Paket "Plus"	
Vehicle Identification number	WVGZZZE2ZPE073910
Mileage (Read)	129,347 km
First registration	3 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2026
(Report not on hand)	
Fuel type	Electric
Power	77 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Mythos Black (Y9T)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	338 Tag(e)
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV291650
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CRK 00011		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,750 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	All-season tires (with run-flat capability) on Light alloy	Bridgestone	5mm / 5mm
2)	255/50 R19 103T	All-season tires (with run-flat capability) on Light alloy	Bridgestone	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 2 USB-C ports on the front (charging power up to 45 W)
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Permanent 4MOTION all-wheel drive
- App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- black roof rails
- Black surround for the infotainment display and central controls
- ESP Electronic Stability Program (incl. ABS Anti-lock Braking System)
- Transmission: 1-speed automatic
- rear window wiper
- ISOFIX mounting points for child seats (mounting points for child seats on the outer rear seats and on the front passenger seat, i-Size compatible)
- Mode 3 Type 2 charging cable, 16 A
- Charging: Maximum DC charging power depends on the traction battery.
- Makeup mirrors in the sun visors
- Centre console
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Package: Sport package "Plus" PSF
- Upholstery: Seat center panels of the front seats and the outer rear seats in "Matrix" fabric
- Radio accessories: Digital radio reception DAB+
- Wheels: Steel wheels (4) 8 J x 19 (tires 235/55 R 19 front, tires 255/50 R 19 rear - wheel covers)
- Keyless Start system (without safe locking)
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner (3 three-point automatic seat belts at the rear - warning tone and light for unfastened seat belts at the front and rear)
- Voice control
- Lane keeping assistant "Lane Assist"
- Telephone interface
- Ambient lighting with logo projection
- Traffic sign recognition
- Prepared for later activation: "Discover Pro" navigation function
- Green thermal insulation glazing, sides and rear
- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- Ambient lighting, 10 colors
- Adaptive Cruise Control (ACC) "stop & go" including speed limiter
- Car2X
- e-Sound (artificially generated engine noise to inform other road users about the approach of the e-vehicle)
- Parking aid (warning signals for obstacles in the front and rear area)
- Driving profile selection
- Back window, heater
- Interior mirror automatically dimming
- "Climatronic" air conditioning system (active combination filter - stationary air conditioning)
- Front and rear headrests (5)
- Charging: 11 kW AC charging power (alternating current)
- LED headlights with automatic headlight control
- Steering wheel: Multifunction steering wheel with touch controls
- Fatigue detection
- Emergency call service (no registration required, service is activated upon delivery)
- Stainless steel pedals in a "Play/Pause" design
- Radio "Ready 2 Discover"
- Radio accessories: 6 + 1 speakers
- Tire pressure monitoring system
- LED taillights
- Windscreen wiper intermittent control
- Electromechanical power steering (speed-dependent control)
- Seats: Armrest for front seats
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat undivided, backrest asymmetrically split and foldable
- Bumpers in body color
- Engine underguard
- First aid kit, warning triangle and high-visibility vest
- Prepared for "We Connect" and "We Connect Plus" (or "VW Connect" and "VW Connect Plus", online update capability)
- Electronic immobilizer
- Central locking including remote control

Extra equipment

- Interior Top Sport "Plus" Platinum Gray PBS
- Package: Assistance Package "Plus" WD4
- Wheels: LM Hamar 8Jx19 Dark Graph.glossy PJA
- Paint finish: Metallic
- Package: Infotainment package "Plus" RD7



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
2	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
3	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint
4	Front bumper	Front bumper - Stone chips - Paint
5	Boot lid / rear door	Boot lid - Scratch(es) - Paint
6	Roof	Roof (Anätzung) - Paint defect - Repair and paint

Wear and tear

No.	Component group	Description
1	Sill - right side	Sill - Scratch(es) - No deduction
2	Door - front left side	Door - Scratch(es) - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.





Figure 22: Misc.




Figure 23: Misc.




Damage 1: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 3: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 3: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 3: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 6: Roof: Roof (Anätzung) - Paint defect - Repair and paint



Damage 6: Roof: Roof (Anätzung) - Paint defect - Repair and paint



Damage 6: Roof: Roof (Anätzung) - Paint defect - Repair and paint