SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FKC-116

2-FKC-116 · COMBI L2H12.0dCi N-CONNECTA N-CONNECTA 2.0 114PS AT · 21 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FKC-116
Manufacturer	NISSAN
Model	Primastar
Model Versions	COMBI L2H12.0dCi N-CONNECTA N-CONNECTA 2.0 114PS AT
Body Type	VAN
Color	Black
Paint Type	Metallic
Production Year	2024
Fuel Type	Diesel

VIN	VNVJ4000673222263
Cylinder Capacity	1.997 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	28-05-2024
Odometer	67.902 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	9

Images
























P
R
N
D
L
M






Accessories

ABS	Electrically adjustable exterior mirrors
Airbags	Fog lights
Audio System	Leather steering wheel
Bluetooth car kit	Manual air conditioning
Central door locking	Rear parking sensors
Centre armrest	Rear view camera
Cruise control	Steering wheel multifunction
Electric windows front	Tow bar

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Toyo	215 mm	65 mm	16 inch	All Season
Rear Left	5 mm	Toyo	215 mm	65 mm	16 inch	All Season
Front Right	3 mm	Toyo	215 mm	65 mm	16 inch	All Season
Rear Right	5 mm	Toyo	215 mm	65 mm	16 inch	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 mm					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Plastic Repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Left Front	Missing	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Missing	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Door-edge chipped	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Rear	Small scratch(es)	Hoekje	Repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Missing	Antenne	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Roof	Dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No




Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No