

» Overview

Order number: 1002370159
Order completed: 24.03.2026 09:37
Report number: 10282605
VIN: WVVZZZ3CZPE050081



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	EstateCar
Make:	Volkswagen
Model:	Passat
Manufacturers and type code:	0603 / BQS
Date of first registration:	16.03.2023
Mileage:	91,386 km
Proof of mileage:	ReadOff
Exterior colour:	Deep Black Perleffekt
Roof colour:	Deep Black Perleffekt
Propulsion:	Front
Fuel:	Diesel
Engine size (cc):	2,000 ccm
Performance:	110 kW (150 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining semi-leather
Interior colour:	Titanschwarz/Titanschwarz/Titanschwarz
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	02.2028
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	526 Day(s)

<p>"Business Premium" package incl. navigation system</p> <p>"Monterey" 8J x 18, Gray Metallic, Volkswagen R, AirStop® tires 235/45 R18</p> <p>12-V outlet in center console rear and in luggage compartment</p> <p>2 beverage holders in front with cover</p> <p>2 USB-C ports in the front, 1 USB-C charging socket on the center console in rear, charging capacity up to 45 W</p> <p>230-V outlet in center console in rear</p> <p>3 head restraints in rear</p> <p>3-point seat belt for center rear seat</p> <p>3-point seat belts for outer rear seats</p> <p>3-point seat belts in front with height adjustment and seat belt pretensioners</p> <p>4 alloy wheels "Monterey" 8J x 18, Gray Metallic</p> <p>4-cylinder diesel engine 2.0 l</p> <p>4-cylinder diesel engine 2.0 l TDI, 110 kW</p> <p>7-speed automatic transmission or dual-clutch transmission DSG, note: PR family EDF</p> <p>8 speakers</p> <p>Adaptive Cruise Control ACC stop & go incl. speed limiter</p> <p>Advanced high-beam control Dynamic Light Assist for LED matrix headlamps</p> <p>Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear</p> <p>AirStop® tires 235/45 R18, low rolling resistance</p> <p>Alternator 140 A</p> <p>App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto</p> <p>Area View incl. rear view camera system</p> <p>Aspherical exterior mirror on driver side</p> <p>Aut. headlight control w/ separate daytime running light, Leaving Home and manual Coming Home feature</p> <p>Auto-dimming interior rearview mirror</p> <p>Automatically-heated washer nozzles in front</p> <p>Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)</p> <p>Basic equipment variant</p> <p>Battery 420 A (70 Ah)</p> <p>Body-colored bumpers, with chrome strip and chrome trims in rear bumper</p> <p>Carpet mats in front and rear</p> <p>Carrier frequency 433.92 MHz-434.42 Mhz</p> <p>Category 0</p> <p>Child safety lock</p> <p>Chrome trims on the side windows</p> <p>Curtain airbag system for front and rear passengers incl. side airbags in front</p> <p>Dark Red LED rear combination lamps, with dynamic turn signal</p> <p>Decorative inserts "Piano Black" for center console</p>	<p>Decorative inserts in brushed aluminum for dashboard and door trim panels</p> <p>Digital radio reception DAB+</p> <p>Disc brakes in front</p> <p>Disc brakes in rear</p> <p>Diversity antenna for FM reception</p> <p>Door trim panel in leather look</p> <p>Driver alert system</p> <p>Driver and front passenger airbag with front passenger airbag deactivation</p> <p>Driving on the right</p> <p>Dual-clutch transmission DSG DQ381</p> <p>Dynamic headlight range control with dynamic cornering light</p> <p>Dynamic Road Sign Display</p> <p>El. opening and closing boot lid</p> <p>Electric auxiliary air heater</p> <p>Electric luggage compartment opening and closing, electric opening for luggage compartment cover</p> <p>Electromechanical parking brake with Auto Hold function</p> <p>Electromechanical speed-sensitive power steering</p> <p>Electronic engine sound</p> <p>Electronic immobilizer</p> <p>Electronic Stability Control and electromechanical brake booster</p> <p>Elegance</p> <p>Elimination of nameplate for engine designation on luggage compartment lid</p> <p>Elimination of Tire Mobility Set</p> <p>Emergency call service; no registration required, service is activated upon delivery</p> <p>Emission standard EU6 AP</p> <p>Equipment options subset for Germany</p> <p>Ext. mirror w/ surround lighting a. fr. passenger ext. mirror lowering funct., folding/heated, auto-dimming on dr. side</p> <p>First aid kit, warning triangle and safety vest</p> <p>Folding luggage compartment floor</p> <p>Folding trailer hitch, with electric release</p> <p>Front and rear scuff plates in stainless steel</p> <p>Front center armrest, height- and longitudinally adjustable, w/ storage comp., 2 vents w/ chrome louvers in rear</p> <p>Front seats with height adjustment, ergoComfort seat on driver side, with electrical backrest adjustment</p> <p>Front vent, power mirror switch, rotary light and power window switches illuminated, with chrome bezels</p> <p>Front-wheel drive</p> <p>Fuel system for diesel engine</p> <p>Fuel tank with a volume of 66 l</p> <p>Gearshift knob in leather</p>
---	---

Heated front seats	Park Distance Control - warning signals for obstacles in the front and rear
Hill Start Assist	Part set without country-specific prescriptive standard
Illuminated vanity mirror in sun visors, extractable sun visors	Pedestrian monitoring
Initial standard fuel filling	Plastic loading edge protection
Inserts of front seats and outer rear seats in ArtVelours microfleece, inner sides of bolsters in leather "Vienna"	Preparation for We Connect and We Connect Plus
Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer	Privacy glass for rear side windows and rear window
Interior lights with switch-off delay and dimmer, 2 LED reading lights in front and 2 in rear	Proactive passenger protection system and lane change system Side Assist
IQ.LIGHT - LED Matrix headlamps with LED sep. daytime running light, dynamic cornering light and dynamic turn signal	Proactive passenger protection system in combination with Front Assist and Side Assist
ISOFIX anchorage points for mounting 2 child seats on rear seats, also for i-Size child seats	Radio
Keyless Start without SAFELOCK	Rain sensor
Laminated safety glass windshield, heat- and sound-insulating	Rear exhaust tailpipe (standard)
Lane change system Side Assist and Rear Traffic Alert	Rear fog light on both sides, back-up light on both sides
Leather multi-function steering wheel with shifting paddles	Rear shock absorption, basic version 1
LED entry/warning lights in front doors	Refrigerant R1234yf
LED front fog lamps and cornering light	Regional code " ECE " for radio
LED light unit in front footwell	Removable luggage compartment protective mat, back of rear bench seat backrest covered with black rubber
Left-hand drive	Right exterior mirror, convex
License plate carrier in front and rear (ECE)	Safety-optimized front head restraints, longitudinally and height adjustable
LongLife Service Regime	Semi-automated driving assistance TravelAssist and lane keeping system Lane Assist
Lower side trims in chrome	Service indicator 30 000 km or 2 years (variable)
Luggage compartment cover extractable and removable, electrically opening	Shock absorption in front
Lumbar supports in front, power- adjustable on driver side, massage feature on driver side	Silver-anodized roof rails
Manual in German (Germany)	Special identification label for EC for M1 passenger vehicles
Mass damper for steering wheel, 36 Hz	Sports comfort seats in front
Mistral Gray headliner	Standard battery/alternator capacity
Mobile phone interface "Comfort" with inductive charging feature	Standard climatic zones
Model update, week 45	Standard engine starter
Model year change 2023 IV	Standard manufacturing sequence
Multifunction camera	Standard paint coating
Multi-function display "Premium" with multi-color display	Standard pedal cluster
Navigation system "Discover Media" incl. Streaming & Internet	Start-stop system with generative braking
Navigation system "Discover Media" incl. Streaming & Internet	Sunshade on rear door window glasses
Net partition	Suspension range 34 installation control only, no requirement forecast
No special edition	Tire Pressure Monitoring System
No special purpose vehicle, standard equipment	Tires without specification of tire brand
Non-folding front passenger seat backrest	Tool kit
Non-smoker's package: tray and 12-V outlet in front	Transport protection film (minimum protection) with additional transport protection measures
Not hot country	Two-tone horn
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Type approval country Germany
Operating permit, alteration	Unsplit rear bench seat, asymmetric folding backrest, center armrest with storage comp. and load-through hatch

Vehicle class differentiation -3G0-

Vehicles with special upgrade measures

Voice control

Wagon

Warning signal and warning light for front and rear seat belts
not fastened

Weight range 4 installation control only, no requirement
forecast

Wheel locks with extended theft protection

Wheelbase

With electronic steering column lock

Without activated carbon canister with SCR

Without Adaptive Chassis Control

Without add. lights (interior lighting)

Without additional front underbody guard

Without additional tires

Without alternative drive system

Without auxiliary heater/parking heater

Without CD/DVD for navigation

Without charging cable

Without child seat

Without clock

Without delivery equipment

Without differential lock

Without ECO function

Without electric motor (hybrid)

Without fire extinguisher

Without front passenger seat control

Without garage door opener

Without headlamp washer system

Without head-up display

Without integrated toll system

Without locking and starting systems

Without preparation for rotating beacon/siren combination

Without preparation for two-way radio installation

Without preparation for VTS (vehicle tracking system)

Without rear spoiler

Without roof insert (standard roof)

Without seat ventilation/massage seat

Without second battery

Without special body measures

Without tie down straps/net/pocket

Without vehicle inlet

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental	Front	Left	Summer	Aluminium	235/45 R 18 94 W	3.0 mm
Continental	Front	Right	Summer	Aluminium	235/45 R 18 94 W	3.0 mm
Continental	Rear	Left	Summer	Aluminium	235/45 R 18 94 W	6.0 mm
Continental	Rear	Right	Summer	Aluminium	235/45 R 18 94 W	6.0 mm

Permitted: Yes

Roadworthy: No

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Windscreen	Stone chip(s)	Replace
2	Side wall RR	Scratch(es)	Paint
3	Alloy rim FR	Broken	Replace Safety relevant damage
4	Bumper F	Scratch(es)	Paint
5	Preparationtime plastic painting	Paint preparation	Execute
6	Tyre FL	Worn	Replace
7	Tyre FR	Worn	Replace
8	Bonnet	Dent(s)	Paintless dent repair
9	Door RL	Dent(s)	Paintless dent repair
10	Bumper corner RR	Scratch(es)	Smart repair
11	Outside rear-view mirror housing R	Scratch(es)	Paint
12	Alloy rim RR	Scratch(es)	Paint
13	Door RR	Scratch(es)	Polish

» Usage Damages

The vehicle shows signs of wear consistent with its age, mileage and purpose.

» Commercial devaluation

Known previous damages:	No
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment**Details of the assignment and the scope of the assessment:**

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVWZZZ3CZPE050081

VIN checked and matches documentation

Vehicle condition:

Dirty

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

No

Testdrive carried out:

No

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4




Rear Right 3/4



Mileage



Tools



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR



Wheel RL



Wheel RR



Central console



Engine compartment



Documents



Interior arrangement



Registration Certificate



Towbar



History Maintenance

Assessment

- Vehicle Inspection Report -


Number: 10282605
From: 24.03.2026



Interior - front



Interior - rear




GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS

1 - Windscreen - Stone chip(s) - Replace



2 - Side wall RR - Scratch(es) - Paint



3 - Alloy rim FR - Broken - Replace
Safety relevant damage




4 - Bumper F - Scratch(es) - Paint



5 - Preparationtime plastic painting - Paint preparation - Execute


6 - Tyre FL - Worn - Replace



7 - Tyre FR - Worn - Replace



8 - Bonnet - Dent(s) - Paintless dent repair



9 - Door RL - Dent(s) - Paintless dent repair



10 - Bumper corner RR - Scratch(es) - Smart repair



11 - Outside rear-view mirror housing R - Scratch(es) - Paint



12 - Alloy rim RR - Scratch(es) - Paint



13 - Door RR - Scratch(es) - Polish

