MACADAM







Jeep Compass (KKL): 2GJN583

Vinnumber:	**ZACPJFCW7RPT00413**	Versionname:	**Compass Summit 1.3T4 240pk/cv 5p eAWD AT6**
First Registrationdate:	**2/01/2025**	Fiscalpower:	
Expertise Mileage:	**54825**	Power Kw:	**132**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar removable**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**235/45/19/99 V**			
	Fr.L.	**Continental: 5 mm**	Fr.R.	**Continental: 3 mm**
	Re.L.	**Continental: 3 mm**	Re.R.	**Continental: 3 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**235/45 R 19 99 V**
Tyre size FR	**235/45 R 19 99 V**
Tyre size RL	**235/45 R 19 99 V**
Tyre size RR	**235/45 R 19 99 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**0**		

MOT certificate, Missing, Replace



Bumper F, Scratch(es), Acceptable





Bonnet, Dent(s), Acceptable




Windscreen, Stone chip(s), Windscreen repair





Outside rear-view mirror housing L, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Step L, Dent(s), Acceptable




Door RL, Scratch(es), Acceptable




Alloy rim RL polished, Scratch(es), Repair and paint (complete)








Charging cable (normal), Missing, Check



Charging cable (fast), Missing, Check



Bumper R, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Repair and paint (complete)




Tyre RR, Tear, Replace




Wing trim RR, Scratch(es), Repair and paint (complete)







Door trim RR, Broken, Replace





Door RR, Dent(s) and scratch(es), Repair and paint (complete)





Alloy rim FR polished, Scratch(es), Repair and paint (complete)





Wing FR, Scratch(es), Acceptable



MACADAM

Onderhoudshistorie van: ZACPJFCW7RPT00413

ALPHABET

Kenteken	2GJN583
Merk Model	Jeep Compass Summit 1.3T4 240pk/cv 5p eAWD AT6
Brandstofsoort	Benzine
Datum deel1	1/2/25

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/22/26	44,661	45000 km	Uitvoeren
5/22/26	44,661	luchtfilter interieur	Vervangen
5/22/26	44,661	oliezeef	Vervangen
12/11/25	29,554	30000 km	Uitvoeren
12/11/25	29,554	luchtfilter	Vervangen
12/11/25	29,554	luchtfilter interieur	Vervangen
12/11/25	29,554	oliezeef	Vervangen
7/8/25	15,633	luchtfilter interieur	Vervangen
7/8/25	15,633	oliezeef	Vervangen
7/8/25	15,633	onderhoud 1e jaar	Uitvoeren