



BMW X1:

Vinnumber:	WBA31AC0105T46506	Versionname:	
First Registrationdate:	5/05/2021	Fiscalpower:	
Expertise Mileage:	110717	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1118
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining artificial leather	Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/50/18/99 W				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 18 99 W
Tyre size FR				225/50 R 18 99 W
Tyre size RL				225/50 R 18 99 W
Tyre size RR				225/50 R 18 99 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0	
Number of charging cables (rapid charge)	0	
Total cost ex VAT		889,22
Ignition key, Missing, Replace		350,09



Seat cover FL, Deformed / Strained, Check	0,00
---	------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Bumper trim R, Scratch(es), Smart repair	116,69
--	--------



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)	422,44
---	--------



Wing FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FR polished, Rust, Acceptable	0,00
---	------

