

DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZ3CZ NE071035	Brand	VOLKSWAGEN	Maintenance date	01/03/2024
Licence Plate	DDO823	Model	Passat-Variant-CB5-2019	Maintenance mileage	56 566 km
Registration date	07/06/2022	Year	2022	Exterior Color	Other
Odometer	140 514 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	01/06/2026	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Rain and light sensor	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element



Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Remote key	✓

DEKRA Automotive Solutions











Tyres

Pirelli 235/45/18 W Summer 3.0 mm			Pirelli 235/45/18 W Summer 3.0 mm	
Pirelli 235/45/18 W Summer 5.0 mm			Pirelli 235/45/18 W Summer 5.0 mm	

Winter kit

Pirelli 215/55/17 T Winter 4.0 mm			Pirelli 215/55/17 T Winter 4.0 mm	
Pirelli 215/55/17 T Winter 7.0 mm			Pirelli 215/55/17 T Winter 7.0 mm	

Damages

1		Part	Complete service track record	2		Part	Headlight trim
		Position	-			Position	Front left
3		Damages	Missing	4		Damages	Scratched
		Severity	-			Severity	-
5		Repair mode	Lumpsum	6		Part	Other accessory
		Position	Front left			Position	Front
7		Damages	Scratched	8		Damages	Not conform
		Severity	-			Severity	-
9		Repair mode	Lumpsum	10		Repair mode	For info
		Position	Front left			Position	Front right
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	For info
		Part	Bumper			Part	Door sill
		Position	Back			Position	Front right
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	-
		Repair mode	Lumpsum Paintworks			Repair mode	For info
		Part	Bumper			Part	Fabric door lining
		Position	Back			Position	Back left
		Damages	Scratched			Damages	Dent & Chips
		Severity	-			Severity	-
		Repair mode	Lumpsum Paintworks			Repair mode	For info
		Part	Door			Part	Steering wheel
		Position	Front left			Position	-
		Damages	Dented			Damages	Damaged
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Smart Repair

DEKRA Automotive Solutions**11**

Part	Roof post A/B/C
Position	Right
Damages	Dented
Severity	-
Repair mode	For info