



RENAULT TRAFIC: FK-640-AY

Vinnumber:	VF1FL000963352985	Versionname:	RENAULT TRAFIC FG GCF L1H1 1200 Energy dCi 125 E6 VU [4P] bvm 6-125CH-5cv (fourgon tA 1A@simple cabine)
First Registrationdate:	11/09/2019	Fiscalpower:	92
Expertise Mileage:	167829	Power Kw:	White
Bodytype:	Transporter	Body colour:	Opaque
Gearbox:	MAN 6 VIT	Paint type:	Black
Transmission:	Front	Interior colour:	Steel
Fueltype:	Diesel	Type of rims (mounted):	Grey
Engine functioning:	Yes	Dashboard color:	
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Tow bar	
Number keys remote	1	Radio	
Windows electric F		Central consol F	
Cruise Control		Roof rack	
Steering wheel multifunctional		Sliding door right-side	
Type of climate control	Manual climate control	Seat cover lining	Lining Other

Tyres

	205/65/16/107 T			
Winter tyres:	Fr.L.	Continental: 40%	Fr.R.	Continental: 25%
	Re.L.	Continental: 25%	Re.R.	Continental: 45%
Tyre profile depth FL				5.7
Tyre profile depth FR				6.5
Tyre profile depth RL				6.6
Tyre profile depth RR				5.1
Tyre size FL				205/65 R 16 107 T
Tyre size FR				205/65 R 16 107 T
Tyre size RL				205/65 R 16 107 T
Tyre size RR				205/65 R 16 107 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	No	Jack	Yes
Seat cover FL, Tear, Repair/replace (lump sum)			



Remote ignition key, Missing, Repair/replace (lump sum)



Steering wheel, Worn, Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Wheel cover FL, Broken, Replace



Wheel cover FR, Broken, Replace



Tyre FR, Out of tolerance, Replace



Outside rear-view mirror housing L, Broken, Replace



Door FL, Scratch(es), Paint



Door trim FL, Scratch(es), Replace



Bumper F, Unclassped, Dismount/Mount



Bumper grille, Broken, Replace



Bumper spoiler F, Scratch(es), Dismount/Mount



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Broken, Replace



Door FR, Dent(s), Repair and paint (complete)



Spare tyre, Missing, Replace



Spare rim, Missing, Replace



Rubber seal for boot lid, Tear, Replace



Boot door panel RR, Dent(s), Repair and paint (complete)



Historique Maintenance

Immatriculation: **FK-640-AY** Date de 1ère immatriculation: **11/09/2019**

Modèle: **Renault TRAFIC FG GCF L1H1 1200 Energy dCi 125 E6 VU [4P] bvm 6-125CH-5cv (fourgon tôle simple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
13/05/2026	166.849	CENTRE DE CONTROLE TECHNIQUE LOURDAIS	CONTROLE TECHNIQUE
09/01/2026	161.825	CONTITRADE FRANCE	REPLACEMENT PNEUS HIVER
02/10/2025	156.065	PYRENEES AUTOMOBILES	COURROIE ACCESSOIRES RPLT
	0		ADBLUE
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		DIVERS REFROIDISSEMENT
	0		RADIATEUR REFROIDISSEMENT MOTEUR RPLT
	0		DIVERS CARROSSERIE
	0		ECHANGEUR AIR HUILE RPLT
	0		RADIATEUR RPLT
	0		GEOMETRIE CTRL
	0		BARRE STABILISATRICE RPLT
	0		PLAQUETTES AR RPLT
	0		BATTERIE RPLT
05/09/2025	155.169	CENTRE DE CONTROLE TECHNIQUE LOURDAIS	CONTROLE TECHNIQUE
30/01/2025	142.158	CONTITRADE FRANCE	REPLACEMENT PNEUS HIVER
03/01/2025	141.010	PYRENEES AUTOMOBILES	DIVERS MOTEUR
	0		INJECTEURS RPLT
	0		RAMPE COMMUNE RPLT
	0		TUYAU DE CARBURANT RPLT
	0		DIVERS ELEC
	0		DIVERS ALIMENTATION
	0		DIAG
	0		ESSAI
	0		VANNE EGR RPLT
	0		BOUGIES DE PRECHAUFFAGE RPLT
11/12/2024	139.666	PYRENEES AUTOMOBILES	LAMPE CODE AVD RPLT
10/10/2024	135.712	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
26/09/2024	135.223	PYRENEES AUTOMOBILES	DISQUES PLAQUETTES AV RPLT
	0		REVISION ET CLIM ET AIR
	0		LIQUIDE DE FREIN

Historique Maintenance

Immatriculation: **FK-640-AY**

Date de 1ère immatriculation: **11/09/2019**

Modèle: **Renault TRAFIC FG GCF L1H1 1200 Energy dCi 125 E6 VU [4P] bvm 6-125CH-5cv (fourgon tôle simple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
06/09/2024	133.197	CENTRE DE CONTROLE TECHNIQUE LOURDAIS	ANTIPOLLUTION
12/01/2024	118.567	CONTITRADE FRANCE	REPLACEMENT PNEUS HIVER
07/12/2023	116.453	PYRENEES AUTOMOBILES	LAMPE RPLT
11/10/2023	112.722	PYRENEES AUTOMOBILES	BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AR RPLT
06/09/2023	110.713	CENTRE DE CONTROLE TECHNIQUE LOURDAIS	CONTROLE TECHNIQUE
18/01/2023	94.503	CONTITRADE FRANCE	REPLACEMENT PNEUS HIVER
10/11/2022	90.542	PYRENEES AUTOMOBILES	REVISION ET CLIM ET CARBURANT
	0		REVISION ET CLIM ET CARBURANT
	0		PLAQUETTES AV RPLT
14/02/2022	70.294	PYRENEES AUTOMOBILES	DIVERS ELEC
	0		ESSAI
	0		RECHARGE CLIM
	0		RADIATEUR REFROIDISSEMENT MOTEUR RPLT
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		DURITE D EAU RPLT
14/01/2022	69.090	CONTITRADE FRANCE	REPLACEMENT PNEUS 4 SAISONS
09/12/2021	66.859	PYRENEES AUTOMOBILES	REVISION ET CLIM
	0		ADBLUE
	0		DISQUES PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		BALAIS ESSUIE GLACE AV
16/04/2021	49.971	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
03/09/2020	32.457	PYRENEES AUTOMOBILES	ADBLUE
	0		REVISION ET CLIM
	0		PLAQUETTES AV RPLT
14/04/2020	18.500	GOODYEAR FRANCE	REPLACEMENT PNEUS ETE
17/02/2020	16.546	CONTITRADE FRANCE	REPARATION DE ROUE