



Skoda Kodiaq (KKL): 2CMN041

Vinnumber:	TMBJB9NS2P8505269	Versionname:	Kodiaq Clever 1.5TSi 150pk/cv 5p DSG7
First Registrationdate:	16/09/2022	Fiscalpower:	
Expertise Mileage:	72349	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	plus 22100 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/65/17/99 V				
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				3.0
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Floor covering FL, Hole, Acceptable



Seat cover R, Stain, Cleaning



Wing trim FL, Scratch(es), Acceptable



Wing FL, Dent(s), Spot repair



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FL, Scratch(es), Acceptable




Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Boot carpet, Stain, Cleaning



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Acceptable



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Kenteken	2CMN041
Merk Model	Skoda Kodiaq Clever 1.5TSi 150pk/cv 5p DSG7
Brandstofsoort	Benzine
Datum deel1	9/16/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/10/26	64,422	bougie	Vervangen
2/10/26	64,422	Inspectie met olie vervanging (vast in	Uitvoeren
2/10/26	64,422	klein materiaal	
2/10/26	64,422	koelwatervloeistof	Bijvullen/-laden
2/10/26	64,422	luchtfILTER interieur	Vervangen
2/10/26	64,422	remblokken achter	Vervangen
2/10/26	64,422	remblokken vooraan	Vervangen
2/10/26	64,422	remvloeistof	Vervangen
2/10/26	64,422	ruitenswisserrubber achter	Vervangen
2/10/26	64,422	ruitenswisserrubber vooraan	Vervangen
2/10/26	64,422	ruitenswisservloeistof	Bijvullen/-laden
10/8/25	57,765	controle niveaus	Uitvoeren
10/8/25	57,765	olie bijvullen	Bijvullen/-laden
6/17/24	30,948	klein materiaal	Uitvoeren
6/17/24	30,948	koelwatervloeistof	Bijvullen/-laden
6/17/24	30,948	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
6/17/24	30,948	ruitenswisservloeistof	Bijvullen/-laden
10/27/23	18,598	controle niveaus	Uitvoeren
10/27/23	18,598	klein materiaal	
10/27/23	18,598	koelwatervloeistof	Bijvullen/-laden
10/27/23	18,598	olie bijvullen	Bijvullen/-laden
10/27/23	18,598	ruitenswisservloeistof	Bijvullen/-laden