



Renault Clio:

Vinnumber:	VF1RJA00667412920	Versionname:	
First Registrationdate:	3/08/2021	Fiscalpower:	
Expertise Mileage:	111549	Power Kw:	87
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	2301
Fueltype:	Petrol		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Tyres

	195/55/16/91 H			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/55 R 16 91 H
Tyre size FR				195/55 R 16 91 H
Tyre size RL				195/55 R 16 91 H
Tyre size RR				195/55 R 16 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	2130,54
Interior, Damaged, Acceptable	0,00



Seat cover R, Stain, Cleaning	29,16
-------------------------------	-------



Bumper F, Scratch(es), Repair and paint (complete)	237,26
--	--------



Wheel cover FL, Scratch(es), Replace	25,50
--------------------------------------	-------



Door RL, Dent(s), Paintless dent repair	95,47
---	-------



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)	466,85
--	--------



Door trim RL, Scratch(es), Replace	74,50
------------------------------------	-------



Wheel cover RL, Scratch(es), Replace	25,50
--------------------------------------	-------



Wing FL, Deformed / Strained, Repair and paint (complete)	306,15
---	--------



Door FL, Bad repair, Check	0,00
----------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Rear window, Scratch(es), Replace	250,00
-----------------------------------	--------



Wheel cover FR, Scratch(es), Replace	25,50
--------------------------------------	-------



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)	161,81
--	--------



Wheel cover RR, Scratch(es), Replace	25,50
--------------------------------------	-------





Door RR, Scratch(es), Polish	0,00
------------------------------	------



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)	407,34
--	--------

