MACADAM







BMW 320e Touring: 2DAK092

Vinnumber:	**WBA6N91080FN20035**	Versionname:	
First Registrationdate:	**13/01/2023**	Fiscalpower:	
Expertise Mileage:	**119917**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**14000 km - 10/2027**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of headlighting	**Headlighting LED**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/45/18/95 Y**			
	Fr.L.	**Bridgestone: 6 mm**	Fr.R.	**Bridgestone: 6 mm**
	Re.L.	**Bridgestone: 5 mm**	Re.R.	**Bridgestone: 5 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/45 R 18 95 Y**
Tyre size FR	**225/45 R 18 95 Y**
Tyre size RL	**255/40 R 18 99 Y**
Tyre size RR	**255/40 R 18 99 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**1**

Ignition key, Not functioning (well), Acceptable



Floor covering FL, Burned, Acceptable






Backrest cover FL, Worn, Acceptable




Bumper F, Scratch(es), Spot repair






Bumper F, Scratch(es), Acceptable




Bumper moulding F, Scratch(es), Acceptable




Windscreen, Stone chip(s), Windscreen repair





Windscreen, Stone chip(s), Acceptable




Alloy rim FL polished, Scratch(es), Repair and paint (complete)







Tyre FL, Deformed / Strained, Acceptable




Step L, Scratch(es), Acceptable




Alloy rim RL polished, Chemical polution, Acceptable






Door FL, Repaired, Check




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)





Boot lid covering R, Scratch(es), Acceptable






Boot carpet, Dirty, Chemical cleaning






Wing RR, Dent(s), Acceptable




Alloy rim RR polished, Scratch(es), Acceptable




Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Bodywork, Paint measurement, Check



Bodywork, Damaged, Check

