



Volvo XC 60:

| | | | |
|------------------------------------|--------------------------|-------------------------|------------------|
| Vinnumber: | YV1UZBFVDM1869266 | Versionname: | |
| First Registrationdate: | 5/05/2021 | Fiscalpower: | |
| Expertise Mileage: | 139954 | Power Kw: | |
| Bodytype: | | Body colour: | Green |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 2610 |
| Fueltype: | Hybrid Petrol | | |
| Maintenance: | OK | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|---------------------------------|------------------------------|------------------------|----------------------------|
| Number of keys total: | 2 | Seats electric F L: | |
| Cruise Control: | | Seats electric F R: | |
| Steering wheel multifunctional: | | Sun Roof electric: | |
| Seats F heated: | | Panoramic roof: | |
| Radio multimedia: | | Luggage cover: | |
| Type of headlighting: | Headlighting LED | Front parking sensors: | |
| Type of GPS: | GPS big screen color | Rear parking sensors: | |
| Type of Lining: | Lining leather | Type of Tow bar: | Tow bar collapsible |
| Type of climate control: | Autom climate control | | |
| Head-up Display: | | | |
| Type of GPS storage: | HD | | |

Limited Technical Inspection

Tyres

| 235/55/19/101 Y | | | | |
|-----------------------|-------|-----------------------|-------|--------------------------|
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |
| Tyre profile depth FL | | | | 3.0 |
| Tyre profile depth FR | | | | 3.0 |
| Tyre profile depth RL | | | | 3.0 |
| Tyre profile depth RR | | | | 3.0 |
| Tyre size FL | | | | 235/55 R 19 101 Y |
| Tyre size FR | | | | 235/55 R 19 101 Y |
| Tyre size RL | | | | 235/55 R 19 101 Y |
| Tyre size RR | | | | 235/55 R 19 101 Y |
| Tyre type FL | | | | Summer |
| Tyre type FR | | | | Summer |
| Tyre type RL | | | | Summer |
| Tyre type RR | | | | Summer |
| Tyre make FL | | | | 261 |
| Tyre make FR | | | | 261 |
| Tyre make RL | | | | 261 |
| Tyre make RR | | | | 261 |

Assistance equipment

| | | | |
|---|------------|-------------|------------|
| Repair kit: | Yes | Compressor: | Yes |
| Number of charging cables (normal): | 0 | | |
| Number of charging cables (rapid charge): | 1 | | |

| | |
|------------------------------------|---------------|
| Total cost ex VAT: | 764,31 |
| Bumper F, Scratch(es), Acceptable: | 0,00 |



Wing RL, Scratch(es), Acceptable 0,00



Door RL, Dent(s), Acceptable 0,00



Door FL, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Charging cable (normal), Missing, Check 0,00



Bumper R, Scratch(es), Repair and paint (complete) 355,89



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Door FR, Dent(s), Acceptable 0,00



Door RR, Scratch(es), Acceptable

0,00

