


Vehicle details

VIN	KNACC81GF L5052757	Brand	KIA	Maintenance date	-
Licence Plate		Model	Niro e-Niro EV ExecutiveLine 5d	Maintenance mileage	-
Registration date	03/12/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	182 771 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	27/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Load cover	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 215/55/17 Summer 7.3 mm



Michelin 215/55/17 Summer 7.3 mm



Hankook 215/55/17 Summer 7.0 mm

Hankook 215/55/17 Summer 7.1 mm

Exterior

1



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	Repair

2



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

3



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

4



Part	Roof
Position	-
Damages	Hail damaged
Severity	-
Repair mode	Repair

5



Part	Bumper moulding
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Lower bumper
Position	-
Damages	Misaligned
Severity	-
Repair mode	Adjust

7



Part	Step plate
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

8



Part	Step plate
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	For info

9



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

10




Part	Window chrome strip
Position	Front left
Damages	Dented
Severity	-
Repair mode	Replace

11



Part	Window chrome strip
Position	Back left
Damages	Dented
Severity	-
Repair mode	Replace

12



Part	Roof post A/B/C
Position	Left
Damages	Hail damaged
Severity	-
Repair mode	Repair

13



Part	Roof post A/B/C
Position	Right
Damages	Hail damaged
Severity	-
Repair mode	Repair