SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Marcel Peeters

2-FXL-867

2-FXL-867 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-FXL-867
Manufacturer	TOYOTA
Model	Corolla Cross
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2024
KW	103
Fuel Type	Hybrid Gasoline

VIN	JTNADADB40J020476
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	26-09-2024
First Registration	26-09-2024
Odometer	79.254 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images































Accessories

- ABS
- Airbags
- Alloy wheels
- Audio System
- Automatic air conditioning
- Bluetooth car kit
- Central door locking
- Centre armrest
- Cruise control
- Electric rear windows
- Electric windows front
- Electrically adjustable exterior mirrors
- Fog lights
- Front & rear parking sensors
- Leather steering wheel
- Rear view camera
- Steering wheel multifunction

Condition

Condition exterior	Adequate
Condition interior	Adequate
Last Maintenance	Unknown
Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Left	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Front Right	3 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Right	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Left Front	Scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Small scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Middenstuk	Plastic Repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Spray	No





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Right	Small scratch(es)	Bekleding	Cloth Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No