



Peugeot 308 (UKL): 2BDL007

Vinnumber:	VF3LCYHZJMS193242	Versionname:	308 SW Active Pack 1.5BlueHDi S&S 130pk/cv 5p
First Registrationdate:	12/10/2021	Fiscalpower:	
Expertise Mileage:	115162	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar fixed
Type of Maintenance book	Maintenance book present		
Type of GPS storage	HD		

Tyres

205/56/16/91 V				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/56 R 16 91 V
Tyre size FR				205/56 R 16 91 V
Tyre size RL				205/56 R 16 91 V
Tyre size RR				205/56 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Bonnet, Stone chip(s), Acceptable			





Bumper R, Bad repair, Repair and paint (complete)



Roof, Dent(s), Paintless dent repair



Kenteken	2BDL007
Merk Model	Peugeot 308 SW Active Pack 1.5BlueHDi S&S 130pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	10/12/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/17/25	93,574	dagrijlamp, dagverlichting	Vervangen
8/5/25	84,527	luchtfILTER interieur	Vervangen
8/5/25	84,527	oliezeef	Vervangen
8/5/25	84,527	onderhoud 12 maand	Uitvoeren
8/5/25	84,527	remvloeistof	Vervangen
4/15/25	77,026	remblokken vooraan	Vervangen
4/15/25	77,026	ruitenswisserrubber achter	Vervangen
4/15/25	77,026	ruitenswisserrubber vooraan	Vervangen
2/25/25	73,764	universele lampen	Vervangen
7/23/24	61,629	60000 km	Uitvoeren
7/23/24	61,629	brandstof hoofdfilter	Vervangen
7/23/24	61,629	luchtfILTER	Vervangen
7/23/24	61,629	oliezeef	Vervangen
7/31/23	39,392	luchtfILTER interieur	Vervangen
7/31/23	39,392	oliezeef	Vervangen
7/31/23	39,392	onderhoud 2e jaar	Uitvoeren
7/31/23	39,392	remvloeistof	Vervangen
10/6/22	19,511	20000 km	Uitvoeren
10/6/22	19,511	oliezeef	Vervangen
6/17/22	13,546	ad blue bijvullen	Bijvullen/-laden
6/17/22	13,546	diagnose	Uitvoeren