



Expertise

Protocol number: 46593963  
Order No. / Reference: 26740946  
Inspection date: 17 Jul 2026

Manufacturer: Ford

Model: Galaxy 2.5 Duratec FHEV TITANIUM

VIN: WF0KXXWPCHPD52194



| Vehicle details                         |                          |
|-----------------------------------------|--------------------------|
| Manufacturer / Type / Model / Equipment |                          |
| Ford Galaxy 2.5 Duratec FHEV TITANIUM   |                          |
| Vehicle Identification number           | WF0KXXWPCHPD52194        |
| Mileage (Read)                          | 103,010 km               |
| First registration                      | 1 Jun 2023               |
| Number of holders                       | 1                        |
| Fuel type                               | Hybrid Petrol / E        |
| Engine displacement / Cylinder          | 2,488 ccm / 4            |
| Power                                   | 110 kW                   |
| Gearbox / Number of gears               | Automatic / 1            |
| Type of drive                           | Front drive              |
| Type of vehicle                         | Van                      |
| Colour / colour code                    | Magnetic-Grau (Metallic) |
| Doors / Seats                           | 5 / 7                    |
| Upholstery type                         | Cloth                    |
| Colour of upholstery                    | Anthracite-Black         |
| Vehicle with smoke odor                 | no                       |
| readiness to drive                      | Roadworthy               |



## Vehicle details

|                                                  |                                     |                                |                                                            |
|--------------------------------------------------|-------------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete            | <b>Next maintenance in</b>     | 56 %                                                       |
| <b>Last service on / at</b>                      | 03/2026 at 95,612 km                |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                               | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                                     | <b>Letter No.</b>              | GT891484                                                   |
| <b>Previous damage / Accident</b>                | Detectable                          | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                          | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | short drive on the company premises | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy                          |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 8566 / BVI 00109                    |                                |                                                            |
| <b>Emission standard</b>                         | EURO6                               | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,595 kg                            | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R17 103V | Summer tyres on Light alloy | Continental  | 5mm / 4mm   |
| 2) | 235/55 R17 103V | Winter tyres on Light alloy | Dunlop       | 6mm / 6mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R17 103V | Winter tyres on Light alloy | Pirelli      | 6mm / 6mm   |
| 2) | 235/55 R17 103V | Summer tyres on Light alloy | Continental  | 2mm / 2mm   |

### Replacement

| Typ     | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|---------|-----------|-------------------------|--------------|-------------|
| Tirefit |           | Expiration date 03/2027 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

## Standard equipment

- Airbag: Passenger airbag deactivation
- Anti-lock braking system (ABS) (with Electronic Stability Program (ESP), Roll Stability Control (RSC) and Traction Control System (TCS))
- Attachment points for safety partition grilles (attachment points 1st row of seats)
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires (in 5x2-spoke design)
- Hill start assist
- Roof rails "aluminum look"
- Lane Assist including Lane Keeping Assist and Driver Alert (warns the driver of an unintentional lane change via short steering wheel vibrations (without activation of the turn signal) - additionally, active steering support assists in returning to the lane)
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot (information about the current status or location of the vehicle as well as control of selected vehicle functions via smartphone with the FordPass app - eCall emergency call system to send an emergency call in the event of an accident or when manually activated - Real-time traffic information - Wi-Fi hotspot (up to 4G/LTE7, for up to 10 mobile devices))
- Interior lighting with delay circuit
- Isofix mounting (on all seats in the 2nd row)
- Electric child safety lock
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Steering column, adjustable in height and reach
- Front and rear reading lights (with LED technology)
- MyKey key system (individually programmable second key) (setting options include: limiting the maximum speed and radio volume, speed warning (when the set speed limit is exceeded), safety assistance systems cannot be deactivated, extended warning system for unfastened seat belts)
- Fog lights with LED technology
- Emergency brake light (pulsating illumination of the brake lights during hard braking)
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Front and rear parking pilot system
- Rain sensor
- Headlight dipped beam with switch-off delay including "greeting function"
- Electro-mechanical power steering (EPAS - Electric Power Assisted Steering)
- Seats: 3rd row of seats with 2 individual seats (FoldFlatSystem) (seat backrests can be folded down individually at the touch of a button and folded up manually - headrests can be lowered)
- Ambient lighting in the front with LED technology (including lighting of the front door handles, audio system console, cup holders and footwell)
- Exterior mirrors painted in body color, electrically adjustable, heated and foldable (with integrated turn signals - ambient lighting)
- Tires: Tire repair kit ((maximum speed of 80 km/h when used))
- third brake light
- Tachometer
- Electric front and rear windows (with all-around closing function)
- Electronic parking brake
- Ford Key Free System (keyless locking/unlocking)
- Ford Power Start function (keyless start, including two passive keys with remote control)
- Cruise control system with intelligent speed limiter (interior mirror, automatically dimming - traffic sign recognition system)
- Transmission: CVT automatic (continuously variable transmission)
- Back window, heater
- rear window wiper
- Intelligent Protection System (IPS) including: - Front airbags for driver and front passenger - Knee airbag for driver - Head and shoulder airbags in the front and for the 2nd and 3rd rows of seats - Side airbags for driver and front passenger - Side airbags on the outer seats of the 2nd row - Seat belt tensioners and belt force limiters in the front - 3-point seat belts in all seats, height-adjustable in the front)
- Steering wheel: Multifunction leather steering wheel
- Front center console with padded armrest (storage compartment and 2 cup holders)
- Ford navigation system including Ford SYNC 3 with AppLink, touchscreen, DAB/DAB+ and FordPass Connect (communication and entertainment with voice control - Android Auto, Apple CarPlay - Bluetooth hands-free system and audio streaming - eCall emergency call system - live traffic - Wi-Fi hotspot - radio/CD player, 2 USB ports, 8 speakers, steering wheel controls - 20.3 cm screen - DAB/DAB+ - acoustic and visual route guidance, dynamic navigation, lane keeping assist, road map for Europe - extended voice control and voice output - Michelin travel guide for Europe - quick address search)
- Upholstery: Cloth
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor (high beam assistant - interior mirror, automatically dimming)
- Seats: 2nd row of seats with 3 individual seats (FoldFlat System) (adjustable longitudinally - seat backrests individually foldable - headrests retractable - easy entry to the 3rd row of seats (Easy Entry))
- Seats: Driver and front passenger seats, 4-way manually adjustable (including manually adjustable lumbar support)
- Seats: Trays on the front seat backrests



- Seats: Comfort seats, front
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- LED daytime running lights
- Velour carpet floor mats (for the 1st, 2nd and 3rd row of seats)
- Electronic immobilizer
- Central locking with remote control (remote luggage compartment release - second folding vehicle key)

- Power outlet: 230-volt connection (150 watts)
- Front bumper painted in body color (rear bumper top painted in body color, bottom painted black)
- Traffic sign recognition system
- Lashing eyes in the luggage compartment
- thermal insulation glazing
- Cigarette lighter (and ashtray in the center console)

### Extra equipment

- Package: Business III (Automatic) (Sony Navigation incl. Ford SYNC 3, AppLink, Touchscreen, Voice Control, Radio/CD Player, MP3-compatible, 2 USB ports, 390-watt premium sound system, 12 speakers, steering wheel remote control, Bluetooth hands-free system, FordPass Connect, eCall, DAB/DAB+, Adaptive LED headlights with glare-free high beam, ACC, Traffic Jam Assist, Pre-Collision Assist, Forward Collision Warning, Emergency Brake Assist, Front and Rear View Camera, Blind Spot Assist, Cross Traffic Alert, Dynamic Distance Control, Power Tailgate with Sensors, Ford Key Free System, Park Assist)
- Paint finish: Magnetic Metallic
- Removable luggage compartment cover
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Sunshade blinds integrated into the rear doors
- Towbar preparation kit (including towbar stabilization function)

### Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | A short maneuvering and shunting exercise was carried out on the company premises.                                                                                           |
| Engine function test | An engine test run was performed.                                                                                                                                            |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                        |

### Value reducing factors

| No. | Component group              | Description                                      |
|-----|------------------------------|--------------------------------------------------|
| 1   | Side panel - rear left side  | Sill - Scratch(es) - Smart repair                |
| 2   | Front bumper                 | Spoiler (Unterhalb) - Scratch(es) - Smart repair |
| 3   | Side panel - rear right side | Side panel - Scratched - Paint                   |
| 4   | Rear bumper                  | Rear bumper - Scratched - Paint                  |
| 5   | Vehicle glazing              | Windscreen (mit Heizung) - Stone chips - Replace |

### Wear and tear

| No. | Component group      | Description                                                                              |
|-----|----------------------|------------------------------------------------------------------------------------------|
| 1   | Trim / covers        | Boot lid - interior trim - Scratch(es) - No deduction                                    |
| 2   | 2nd wheel set        | 2 tyres (Über 2mm Profiltiefe) - No deduction                                            |
| 3   | Wheel / tyres        | Tyres - complete set (Vorderachse Sommerreifen; Hinterachse Winterreifen) - No deduction |
| 4   | Bonnet               | Bonnet - Stone chips - No deduction                                                      |
| 5   | Mudguard - left side | Mudguard - left side - Stone chips - No deduction                                        |

The vehicle shows signs of wear and tear commensurate with its age and use.



## Previous damages

| No. | Previous damage                                           | Extent of damage (Net) |
|-----|-----------------------------------------------------------|------------------------|
| 1   | Side right, Provided by user / customer, from 29 Nov 2024 | 650,32 €               |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Der beiliegende Radsatz ist kein Bestandteil der Ausstattung.



**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - front



Figure 7: Interior - rear



Figure 8: Interior - rear



Figure 9: Instrument cluster



Figure 10: Instrument cluster



Figure 11: Instrument panel



Figure 12: Instrument panel



Figure 13: Interior 360° view



Figure 14: Cargo area



Figure 15: Cargo area



Figure 16: VIN



Figure 17: Mounted tyres



Figure 18: Mounted tyres



Figure 19: Documents



Figure 20: Documents




Figure 21: Documents



Figure 22: Additional tyres




Figure 23: Navigation



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



**Figure 37:** Misc.



**Figure 38:** Misc.



**Damage 1:** Side panel - rear left side: Sill - Scratch(es) - Smart repair



**Damage 1:** Side panel - rear left side: Sill - Scratch(es) - Smart repair



**Damage 2:** Front bumper: Spoiler (Unterhalb) - Scratch(es) - Smart repair



**Damage 2:** Front bumper: Spoiler (Unterhalb) - Scratch(es) - Smart repair



**Damage 2:** Front bumper: Spoiler (Unterhalb) - Scratch(es) - Smart repair



**Damage 3:** Side panel - rear right side: Side panel - Scratched - Paint




**Damage 3:** Side panel - rear right side: Side panel - Scratched - Paint




**Damage 3:** Side panel - rear right side: Side panel - Scratched - Paint



**Damage 3:** Side panel - rear right side: Side panel - Scratched - Paint




**Damage 4:** Rear bumper: Rear bumper - Scratched - Paint



**Damage 4:** Rear bumper: Rear bumper - Scratched - Paint



**Damage 5:** Vehicle glazing: Windscreen (mit Heizung) - Stone chips - Replace



**Damage 5:** Vehicle glazing: Windscreen (mit Heizung) - Stone chips - Replace



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0KXXWPCHPD52194

Hersteller / Modell: FORD FORD Galaxy 2.5 Duratec FHEV TITANIUM

| Datum      | KM-Stand | Beschreibung                                                                                                       |
|------------|----------|--------------------------------------------------------------------------------------------------------------------|
| 23.03.2026 | 95.612   | Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern    |
| 28.10.2025 | 80.481   | Reparatur Sonstiges                                                                                                |
| 12.09.2025 | 77.286   | Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Systemtest/Eigendiagnose; Systemtest/Eigendiagnose; Wartung Sonstiges |
| 09.07.2025 | 72.012   | Systemtest/Eigendiagnose                                                                                           |
| 04.06.2025 | 69.226   | Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst                                                        |
| 07.03.2025 | 59.953   | Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges                                                     |
| 14.08.2024 | 43.280   | Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern    |
| 18.12.2023 | 18.840   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                           |