








· 1.0 TSI 110pk R-Line · 12 June 2026 ·

Specifications

		Fuel Type	Gasoline
Manufacturer	VOLKSWAGEN	VIN	WVGZZZC1ZNY066037
Model	T-Cross	Cylinder Capacity	999 ^{cm³}
Model Versions	1.0 TSI 110pk R-Line	Transmission Type	Handmatig geschakelde transmissie6
Body Type	SUV	MOT	22-06-2026
Color	Silver	First Admission	22-06-2022
Paint Type	Metallic	First Registration	22-06-2022
		Odometer	217.560 ^{Km}
Production Year	2022	Numer Of Keys	2
KW	81	Interior	Darkgrey

Images





Accessories

ABS

Airbags

Alloy wheels

ASR

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable & heated exterior mirrors

ESP

Leather steering wheel

Navigation system

Parking sensors

Rear view camera

Roller cover / parcel shelf

Roof rails

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Vredestein Quatrac	205 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Rear Left	5 ^{mm}	Vredestein Quatrac	205 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Front Right	6 ^{mm}	Vredestein Quatrac	205 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Rear Right	5 ^{mm}	Vredestein Quatrac	205 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Homecomer					

Damages

Acceptable



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Damaged	lichte slijtagesporen interieur bekleding en rubbers	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Mirror - Rightside	Broken	binnenring	Replace	No



Damage Part
spoiler FB

Damage Type
Damaged

Repair Type
Replace

Acceptable
No



Damage Part
Fender - Front Left

Damage Type
Small dent(s)

Repair Type
Restyle / Polish

Acceptable
No



Damage Part
Alloy - Left Front

Damage Type
Small scratch(es)

Repair Type
Acceptable

Acceptable
Yes