MACADAM









VOLKSWAGEN GOLF: GE-810-XW

Vinnumber:	**WVWZZZCDZNW158170**	Versionname:	**VOLKSWAGEN GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**
First Registrationdate:	**25/02/2022**	Fiscalpower:	
Expertise Mileage:	**125197**	Power Kw:	**81**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Hybrid**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Grey**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Tow bar	
Number keys remote	**1**	Radio	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	**Autom climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**205/55/16/91 H**			
	Fr.L.	**Michelin: 65%**	Fr.R.	**Michelin: 65%**
	Re.L.	**Michelin: 30%**	Re.R.	**Michelin: 30%**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**3.9**
Tyre profile depth RL	**6.3**
Tyre profile depth RR	**6.3**
Tyre size FL	**205/55 R 16 91 H**
Tyre size FR	**205/55 R 16 91 H**
Tyre size RL	**205/55 R 16 91 H**
Tyre size RR	**205/55 R 16 91 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Emergency spare wheel	**Yes**	Jack	**Yes**

Remote ignition key, Missing, Repair/replace (lump sum)




Door seal FL, Tear, Replace




Interior, Stain, Cleaning








Seat belt RR, Tear, Replace




Tyre FL, Out of tolerance, Replace





Alloy rim FL, Scratch(es), Acceptable







Alloy rim RR, Scratch(es), Repair/replace (lump sum)






Alloy rim FR, Scratch(es), Repair/replace (lump sum)






Tyre FR, Out of tolerance, Replace





Bumper F, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable







ALPHABET

Historique Maintenance

Immatriculation: **GE-810-XW** Date de 1ère immatriculation: **25/02/2022**

Modèle: **Volkswagen GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
28/07/2026	121.406	GGE ST CHRISTOPHE SEAT BREST	Essuie-Glace
			BOUGIES ALLUMAGE RPLT
			REVISION
			BALAI ESSUIE GLACE AR
			Bougie d'allumage (Remplacement)
			Pièce principale de moteur
			Composant Electrique
			Pieces
			Petite Fourniture moteur
			Pieces
			Pièce principale de moteur
			Petite Fourniture moteur
			Petite Fourniture moteur
			Petite Fourniture moteur
			Petite Fourniture moteur
			Entretien - Standard
			Essuie - Glace Arrière (Remplacement)
29/10/2025	92.462	GARAGE ST CHRISTOPHE	LIQUIDE DE FREIN
			BALAIS ESSUIE GLACE AV
			REVISION
20/05/2025	77.743	GARAGE ST CHRISTOPHE	DIAG
			DIVERS MOTEUR
07/08/2024	60.409	VELIZY AUTOMOBILES	BALAI ESSUIE GLACE AR
			LIQUIDE LAVE GLACE
			PILE DE CLE RPLT
			GRAISSAGE TOIT OUVRANT CTRL
			DIVERS CARROSSERIE
			LIQUIDE DE FREIN
			REVISION ET CLIM ET AIR ET BOUGIES
			BALAIS ESSUIE GLACE AV
12/12/2023	49.608	VELIZY AUTOMOBILES	DISQUES PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT

Historique Maintenance

Immatriculation: **GE-810-XW** Date de 1ère immatriculation: **25/02/2022**

Modèle: **Volkswagen GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
22/02/2023	32.364	ADVANCE	REVISION