



Peugeot 308: [redacted]

Vinnumber:	<b>VR3FPHNSTNY513953</b>	Versionname:	
First Registrationdate:	<b>2/06/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>83395</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>White</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1215</b>
Fueltype:	<b>Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options

Number of keys total	<b>1</b>	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	<b>Headlighting LED</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>	Type of Tow bar	<b>Tow bar removable</b>
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection

Tyres

225/40/18/92 H				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Firestone: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/40 R 18 92 H
Tyre size FR				225/40 R 18 92 H
Tyre size RL				225/40 R 18 92 H
Tyre size RR				225/40 R 18 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				258
Tyre make RL				2480
Tyre make RR				258

Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	4145,90
-------------------	---------

Ignition key, Missing, Replace	350,09
--------------------------------	--------



Centre console, Scratch(es), Acceptable 0,00



Seat cover FL, Burned, Smart repair 116,69



Backrest cover FL, Damaged, Smart repair 116,69



Seat cover FR, Stain, Cleaning 29,16



Bumper F, Dent(s) and scratch(es), Repair and paint (complete) 356,09



Fog lamp L, Scratch(es), Replace 96,32



Bumper moulding F, Scratch(es), Repair and paint (complete) 161,81



Bonnet, Dent(s), Acceptable 0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Wing RL, Bad repair, Check 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Tyre FL, Deformed / Strained, Replace 180,98



Bumper R, Dent(s), Repair and paint (complete) 356,09



Rear window, Scratch(es), Replace 285,47



Bumper moulding R, Dent(s) and scratch(es), Repair and paint (complete) 161,81



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Door FR, Dent(s), Repair and paint (complete) 505,30



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Wing RR, Dent(s), Repair and paint (complete) 431,58



Tyre RR, Deformed / Strained, Replace 180,98



Roof, Dent(s), Acceptable 0,00

