



## 2-EWU-617


2-EWU-617 · Move! 1.0 TSI 110cv DSG unicolor · 30 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-EWU-617	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ7RR082890
Model	Arona	Cylinder Capacity	999 <sup>cm<sup>3</sup></sup>
Model Versions	Move! 1.0 TSI 110cv DSG unicolor	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	22-02-2024
Color	Blue	Odometer	88.009 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	81	Number Headrests	5

## Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate


Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 <sup>mm</sup>	Vredestein	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Rear Left	4 <sup>mm</sup>	Hankook	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Front Right	6 <sup>mm</sup>	Vredestein	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Rear Right	4 <sup>mm</sup>	Hankook	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Spare Tire Type	Compressor					

## Damages



Damage Part

Damage Type

Repair Type


Acceptable

Reardoor - Left

Stonechipping

Touch-up / Polish

No



Damage Part

Damage Type

Repair Type


Acceptable

Frontdoor - Left

Door-edge chipped

Acceptable

Yes



Damage Part

Damage Type

Repair Type


Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type


Acceptable

Overfender

Scratch(es)

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable


Roof

Small dent(s)

Dakstijl

Restyle

No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Front Right	Small scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Small dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Dent(s)	Dakstijl	Panelbeating & Spray	No



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Left

Small scratch(es)

Touch-up / Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Rear seat

Stains & dirt

Cleaning

No